

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TP ConPac
Daphne

AEON PAINTING WERKS
356A GEYLANG RD
SINGAPORE 389375

TAX INVOICE

Repair Code : CLM16518

Date in : 11/02/2025

Vehicle Num. : GBJ8209L

Model : TOYOTA HIACE DX 2.8 AUTO

Chassis/Eng# : GDH2011022936/1GD8409578

Contact : 96938511 93476150

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Delud</i>	1	673.10	✓ 673.10
REAR BUMPER LOWER BRACKET <i>2 piece but</i>	4	48.00	36. 192.00
REAR BUMPER SIDE RETAINER L/R <i>Lit could</i>	2	47.00	94.00
REAR END PANEL (OUTER) <i>Regis</i>	1	743.00	+ 743.00
REAR FLOOR PANEL TOP PLATE <i>Ren</i>	1	195.00	+ 195.00
REAR FLOOR PANEL TOP PLATE COVER L/R <i>Ren</i>	2	88.00	+ 176.00
REAR ^{LH} TAILLAMP <i>could</i>	1	458.10	✓ 458.10
REAR ^{RH} TAILLAMP LOWER GARNISH <i>could</i>	1	157.00	✓ 157.00
REAR RH TAILLAMP LOWER GARNISH RETAINER <i>Ren</i>	1	53.00	+ 53.00
REAR SPARE TYRE CARRIAGE <i>Free</i>	1	519.00	+ 519.00
REAR SPARE TYRE CARRIAGE BRACKET	1	79.00	+ 79.00
REAR STEP PANEL <i>Dented</i>	1	175.40	✓ 175.40
REAR TAILGATE <i>Dented</i>	1	3045.60	2350. 3045.60
REAR TAILGATE 'LOGO' EMBLEM <i>Ren</i>	1	63.00	✓ 63.00
REAR TAILGATE DAMPER L/R	2	214.00	+ 428.00
REAR TAILGATE HINGES L/R	2	67.00	+ 134.00
REAR TAILGATE INNER TRIM BOARD <i>Ren</i>	1	469.00	+ 469.00
REAR TAILGATE LOCK STRIKER	1	53.00	+ 53.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

AEON PAINTING WERKS
356A GEYLANG RD
SINGAPORE 389375

Contact : 96938511 93476150

TAX INVOICE

Repair Code : CLM16518

Date in : 11/02/2025

Vehicle Num. : GBJ8209L

Model : TOYOTA HIACE DX 2.8 AUTO

Chassis/Eng# : GDH2011022936/1GD8409578

REAR TAILGATE MECHANISM LOCK	<i>Replaced</i>	1	264.00	<i>/</i>	264.00
REAR TAILGATE MECHANISM LOCK COVER	<i>changed</i>	1	123.20	<i>/</i>	123.20
REAR TAILGATE OUTER GARNISH	<i>new</i>	1	151.20	<i>x</i>	151.20
REAR TAILGATE WEATHER STRIP	<i>new</i>	1	391.00	<i>+</i>	391.00
Subtotal before discount					8,636.60
Percentage discount 25%					2,159.15
Sub-total 1					6,477.45
REAR BUMPER CLIPS - SET	<i>new</i>	1	80.00	<i>30</i>	80.00
REAR BUMPER NUMBER PLATE	<i>new</i>	1	25.00	<i>+</i>	25.00
REAR BUMPER NUMBER PLATE FRAME	<i>new</i>	1	50.00	<i>+</i>	50.00
REAR BUMPER REVERSE SENSOR - SET	<i>Replaced</i>	1	280.00	<i>200</i>	280.00
REAR TAILGATE '70KM' STICKER	<i>new</i>	1	25.00	<i>15</i>	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	<i>new</i>	1	50.00	<i>+</i>	50.00
Subtotal before discount					510.00
Percentage discount 0%					0.00
Sub-total 2					510.00
Parts-total					6,987.45

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

AEON PAINTING WERKS
356A GEYLANG RD
SINGAPORE 389375

Contact : 96938511 93476150

TAX INVOICE

Repair Code : CLM16518

Date in : 11/02/2025

Vehicle Num. : GBJ8209L

Model : TOYOTA HIACE DX 2.8 AUTO

Chassis/Eng# : GDH2011022936/IGD8409578

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

✓ 80.00
120 130.00
40 80.00
400 700.00
600 800.00
30 80.00
60 80.00

1330

Labour Total

1,970.00

Parts & Labour Total

8,957.45

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan Ly
2/2 11/02/25

04 Days

Total: 4835.10

2/5 3.8K