



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24060034/Avp3
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	11/06/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNP 5209H	Veh. Inspected	PC 9458Z
Policy No.	-	Coverage	0
Claim No.	AVS24/1786	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	11/06/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE COMMUTER	C.C	2754
Engine No.	1GD8458704	Year of Reg.	11/11/2020
Chassis No.	GDH2232002376	Colour	WHITE
Odometer	115500 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15C	YOKOHAMA	6
L/H Front Tyre	195 R15C	YOKOHAMA	6
R/H Rear Tyre	195 R15C	YOKOHAMA	6
L/H Rear Tyre	195 R15C	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/06/2024	Inspection Date	11/06/2024
Survey held at	GREEN FOREST AUTOMOBILE 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days