

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

SUNNYBAY TRANSPORT PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

10th JUNE 2024

Accident date: 06th JUNE 2024
Estimated repair cost for vehicle no: PC9458Z TOYOTA HIACE

S/n	Qty	Items	U/price	Amount
1	1	Front side panel- LH <i>Defect</i>		\$285.00 ✓
2	1	Front side panel mirror -LH <i>ht</i>		\$255.00 ✓
3	1	Front head lamp -LH <i>ren</i>		\$355.00 +
4	1	Front head lamp bracket -LH <i>ren</i>		\$115.00 +
5	1	Front side lamp -LH <i>ren</i>		\$178.20 +
6	1	Front bumper <i>ren</i>		\$725.20 +
7	2	Front bumper side bracket <i>ren</i>	\$78.20	\$156.40 +
8	1	Front bumper bracket-LH <i>ren</i>		\$188.00 +
9	1	Front bumper air-duct <i>ren</i>		\$187.30 +
10	1	Front L/H Door <i>Defect</i>		\$1,050.00 ✓
11	1	Front L/H Door body logo <i>ren</i>		\$350.00 <i>250 (sw)</i>
12	1	Front L/H Door Inner Lock <i>ren</i>		\$265.80 +
13	1	Front L/H Side Mirror <i>ht</i>		\$380.00 ✓
Subtotal :-				\$4,490.90

Labour charges

To Check Wiring System	\$60.00 <i>30</i>
Tuff kote	\$100.00 +
Panel beating	\$400.00 <i>300</i>
Spray painting	\$400.00 <i>300</i>

Subtotal :- \$960.00
Total:- \$5,450.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin
2/8 14/06/24
03 Days