

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Chan Yong Tat
C/o: Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-24
Paya Ubi Industrial Park, Singapore 408934

Date : 7 February 2020
Our ref : TWG/01/2001/TP

Accident Date : 14 December 2019
Inspection Date : 02 January 2020
Repairer Name : Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-24
Paya Ubi Industrial Park, Singapore 408934

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SLR 5300 P
Make / Model : Nissan GTR
Chassis No : R35005101
Engine No : VR38007409A

Year / Capacity : 2008 / 3799 cc
Colour : Purple
Mileage : 162262

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Michelin	285/55 R20	5 mm	Sport
Front Offside	: Michelin	285/55 R20	5 mm	Sport
Rear Nearside	: Michelin	285/55 R20	5 mm	Sport
Rear Offside	: Michelin	285/55 R20	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 45 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle
and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 14,200.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Vehicle Registration No: SLR 5300 P

Our Ref No: TWG/01/2001/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front o/s headlamp	Damage	\$ 4,997.30	\$ 4,997.30	HH
			\$ 4,997.30	\$ 4,997.30	
		Less 10%	\$ 499.73	\$ 499.73	
	Total Cost - List Items		\$ 4,497.57	\$ 4,497.57	

SPECIAL NETT ITEMS

1	Front bumper "TOP SECRET"	Damage	\$ 6,800.00	\$ 6,800.00	HH
1	Front bumper lower spoiler	Damage	\$ 2,800.00	\$ 2,800.00	HH ✓
1	Front bumper sticker "Hexis Forged Carbon"	Damage	\$ 1,500.00	\$ 1,500.00	HH
1	Front bumper sticker - Purple	Damage	\$ 1,000.00	\$ 1,000.00	HH
1	Front number plate with holder	Damage	\$ 50.00	\$ 50.00	HH
	Total Cost - Special Nett items		\$ 12,150.00	\$ 12,150.00	HH

Total cost of parts

\$ 16,647.57 \$ 16,647.57

Vehicle Registration No: SLR 5300 P

Our Ref No: TWG/01/2001/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 16,647.57	\$ 16,647.57

LABOUR

- | | | | |
|---|--|-------------|---|
| 1 | To check wiring , lighting and resetting headlamps focussing. | \$ 80.00 | \$ 50.00 <i>NH</i> |
| 2 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident. | \$ 1,000.00 | \$ 600.00
<i>300/-</i> |
| 3 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident. <i>— small strip on lower lip.</i> | \$ 800.00 | \$ 500.00
<i>120/-</i>
300/-
<i>HA</i> |

GRAND TOTAL

\$ 18,527.57 \$ 17,797.57

3220.00

L/S 2,550/-

2 dys.

~~PR is only one item~~

NH = photos show no damage.

Number plate not change.

in after repair.

Lip most protruded part of body.

Vehicle Registration No: SLR 5300 P

Our Ref No: TWG/01/2001/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 14,200.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K/H
Automotive Appraiser