

Your Ref : -

Date: 23<sup>rd</sup> Jul 2024

Our Ref : CS/TP24070030/Evce2

**M/s SITI MARYAM BTE A RAHMAN**  
Blk 428 Pasir Ris Drive 6 #10-31  
Singapore 510428  
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBP 4788B  
ACCIDENT ON 27/11/2023**

Instruction was received to inspect the vehicle Reg. No. FBP 4788B. The inspection was conducted on 01/07/2024 at the premises of M/s Tuck Life Pte Ltd, 25 Kaki Bukit Road 4 #01-68 Synergy@ KB, Singapore 417800.

The following vehicle information was recorded:

Registration Number	: FBP 4788B
Make/Model	: Yamaha Sniper T150
Year of Registration	: 2019
Body Colour	: Multi Colour
Chassis Number	: MH3UG0740K0152705
Engine Capacity	: 150 cc
Speedometer Reading	: Not Available

The vehicle sustained damages at the front. rear portion, n/s and o/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 8,000.00 (estimated at the time of inspection)
Less: LTA Reimbursement Value (RV)	(S\$ 1,670.00 )
Nett Liability	<u>S\$ 6,330.00</u> =====

Vehicle Inspected By:



CHEN TSUE YEE  
Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.