



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: JOANNE YONG			Ref: CS/FCI24120330/Uqp3m4(N) Date: 10/01/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 8674S	Veh. Inspected	SHB 5925T
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24011150MFCT	Excess (\$)	0.00
	Assign From	CAROLINE	Assign Date	23/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JTDKB3FU703091765	Colour	MAROON
	Odometer	442740 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65R15	BEARWAY	6 mm
	L/H Front Tyre	195/65R15	BEARWAY	6 mm
	R/H Rear Tyre	195/65R15	GREENTRAC	6 mm
	L/H Rear Tyre	195/65R15	GREENTRAC	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/12/2024	Inspection Date	23/12/2024
	Survey held at	STRIDES PREMIER AUTOMOTIVE SERVICES PL 23 CHANGI SOUTH AVE 2 SINGAPORE 486443		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	