


Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/01/2025
User ID : PohSuan

Section A - Accident Details	
Registration Number	SHB5925T
Case Reference Number	TAX/12/24/2065
Registration Date	1/Dec/2020
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAN CHIN HIANG
Type of Accident	Head To Side
Accident Date and Time	19/Dec/2024 11:23 PM
Accident Reported Date and Time	20/Dec/2024 9:53 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24120056
Special Instruction to ARC,if any	DAMAGE TO THE RIGHT SIDE OF TAXI TOWED IN
Prepared Date and Time	20/Dec/2024 10:10 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$800.00
Total Spray Cost	\$1,794.00	\$850.00
Total Spare Part Cost	\$6,806.12	\$3,222.31
Total Other Cost	\$776.00	\$200.00
TOTAL COST	\$10,728.12	\$5,072.31
Lump Sum Total	\$10,750.00	\$5,050.00 (L/S)
Number of Repair Days	8.0	5.0
Prepared / Adjusted By	Boon Chew Tay	MARCUS CHUA (LKK) / FCI
ARC / Surveyor Sign Off Date	23/12/2024 4:20 PM	23/12/2024 12:48 PM
Signature		
Remarks	Expected length of repair (days) = 5 days Expected release date of vehicle after repair (Subject to approval from FM and without Supplementary) = 31-12-2024 REQ TOWING INVOICE L/S REPAIR / AFTER PAINT PHOTO . FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR MARCUS CHUA (LKK) / HP : 9009 6608 / Email : marcuschua@lkkauto.com	

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/01/2025
User ID : PohSuan

Section C - Quotation and Accident Invoice Details			
Quotation Number	E24120185	Invoice Number	
Quotation Date	20/12/2024	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,352.00	\$800.00
Total Labour	\$1,352.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	\$100.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY CENTRE PILLAR RH	\$220.00	\$100.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY DOOR HANDLE	\$220.00	\$50.00
Total Spray Painting & Panel Beating	\$1,794.00	\$850.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$120.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$776.00	\$200.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		75850-47910	MOULDING ASSY, BODY ROCKER PANEL , RH	1.00	\$649.10	25.00	\$486.83	Replace	Replace
		65637-47060	LINER, REAR FENDER , RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace	Replace
		69803-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	0.00	\$223.50	0.00	\$0.00	Replace	Check
		85720-47150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Check
		68630-47050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Check

✓
X
✓
X
X
X
X

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/01/2025

User ID : PohSuan

		68770-52031	HINGE ASSY, REAR DOOR , LOWER RH	1.00	\$93.90	25.00	\$70.43	Replace	Replace	√
		68750-20122	HINGE ASSY, REAR DOOR , UPPER RH	1.00	\$107.00	25.00	\$80.25	Replace	Replace	√
		69050-52250	DOOR LOCK REAR , RH	1.00	\$607.90	25.00	\$455.92	Replace	Replace	√
		69410-20110	DOOR LOCK STRIKER	0.00	\$42.60	0.00	\$0.00	Replace	Not Given	X
		69211-47021-A1	DOOR OUTER HANDLE REAR , RH	0.00	\$105.50	0.00	\$0.00	Replace	Not Given	X
		67871-47051	WEATHERSTRIP, REAR DOOR RH	0.00	\$194.60	0.00	\$0.00	Replace	Check	X
		62551-47020-C0	GARNISH, REAR SEAT SIDE, RH	0.00	\$261.60	0.00	\$0.00	Replace	Check	X
		67917-47070-C0	PLATE, REAR DOOR SCUFF, RH	0.00	\$123.00	0.00	\$0.00	Replace	Check	X
		62331-47050	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	0.00	\$317.10	0.00	\$0.00	Replace	Check	X
			STICKER LOGO (RR DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
		67003-47211	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	Replace	√
		85710-47140	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given	X
		69801-21020	DOOR FRONT WINDOW REGULATOR SUB-ASSY, RH	0.00	\$257.80	0.00	\$0.00	Replace	Not Given	X
		68730-12120	HINGE LOWER RHF, DOOR	0.00	\$120.00	0.00	\$0.00	Replace	Not Given	X
		68710-12151	HINGE UPPER RHF, DOOR	0.00	\$105.50	0.00	\$0.00	Replace	Not Given	X
		69210-47041-A1	DOOR OUTER HANDLE FRONT , RH	1.00	\$423.20	100.00	\$0.00	Replace	Repair	R
		69030-47100	LOCK ASSY, FRONT DOOR RH	0.00	\$655.30	0.00	\$0.00	Replace	Not Given	X
		67861-47060	WEATHERSTRIP, FRONT DOOR RH	0.00	\$250.70	0.00	\$0.00	Replace	Not Given	X
		68610-47040	CHECK ASSY, FRONT DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X
		61311-47050	PILLAR, CENTER BODY, OUTER RH	1.00	\$349.50	100.00	\$0.00	Replace	Repair	R
			STICKER LOGO (FRT DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
		67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	Replace	√
Total					\$11,303.50		\$4,027.89			

Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Total										

	4,027.89	
	-20%	
	3222.31	L/S \$5,050/-
+	800.00	
+	1050.00	
	5,072.31	