

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB5925T
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Dec 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Maroon
Manufacturing Year:	2020
Engine No.:	2ZR2G87272
Chassis No.:	JTDKB3FU703091765
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	01 Dec 2020
First Registration Date:	01 Dec 2020
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Nov 2028
PARF Rebate Amount:	\$10,897.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$29,843.00
COE Rebate Amount:	\$14,683.00
Total Rebate Amount:	\$25,580.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Dec 2024

OK

FCI

SMRT Accident Vehicle Repair Estimates

- LKK Auto Consultants hereby notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged parts in a prominent
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Not Authorised
meray
23/12/24
1/49

5 days
telephonic APN

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera
User ID

Section A - Accident Details	
Registration Number	SHB5925T
Case Reference Number	TAX/12/24/2065
Registration Date	1/12/2020
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAN CHIN HIANG
Type of Accident	Head To Side
Accident Date and Time	19/12/2024 11:23 PM
Accident Reported Date and Time	20/12/2024 9:53 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24120056
Special Instruction to ARC, if any	DAMAGE TO THE RIGHT SIDE OF TAXI TOWED IN
Prepared Date and Time	20/12/2024 10:10 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$0.00
Total Spray Cost	\$1,794.00	\$0.00
Total Spare Part Cost	\$6,416.66	\$0.00
Total Other Cost	\$776.00	\$0.00
TOTAL COST	\$10,338.66	\$0.00
Lump Sum Total	\$10,350.00	\$0.00
Number of Repair Days	8.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	20/12/2024 10:30 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicab
TO REPAIR RH PORTION	\$1,352.00	200 800
Total Labour	\$1,352.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO RESPRAY FRONT DOOR RH	\$378.00	200
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	100
TO RESPRAY RH REAR DOOR	\$378.00	200
TO RESPRAY CENTRE PILLAR RH	\$220.00	100
TO RESPRAY REAR FENDER RH	\$378.00	200
TO RESPRAY DOOR HANDLE	\$220.00	50
Total Spray Painting & Panel Beating	\$1,794.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TOWING CHARGE	\$56.00	3,11 ?
TO WASH AND VACUUM	\$60.00	17 X
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	20
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	60
TO TRANSFER DOOR MECHANISM	\$240.00	120
TO REPLACE SUNDRY PARTS	\$100.00	11 X
Total Other Costs	\$776.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	h. 600 ✓
			STICKER LOGO (FRT DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	nu ✓
		61311-47050	PILLAR, CENTER BODY, OUTER RH	1.00	\$349.50	25.00	\$262.13	Replace	R X
		68610-47040	CHECK ASSY, FRONT DOOR	1.00	\$199.40	25.00	\$149.55	Replace	nn X
		67861-47060	WEATHERSTRIP, FRONT DOOR RH	1.00	\$250.70	25.00	\$188.02	Replace	nn X
		69030-47100	LOCK ASSY, FRONT DOOR RH	1.00	\$655.30	25.00	\$491.47	Replace	nn X
		69210-47041-A1	DOOR OUTER HANDLE FRONT , RH	1.00	\$423.20	25.00	\$317.40	Replace	R X
		68710-12151	HINGE UPPER RHF, DOOR	1.00	\$105.50	25.00	\$79.13	Replace	nn X
		68730-12120	HINGE LOWER RHF, DOOR	1.00	\$120.00	25.00	\$90.00	Replace	nn X
		69801-21020	DOOR FRONT WINDOW REGULATOR SUB-ASSY, RH	1.00	\$257.80	25.00	\$193.35	Replace	nn X
		85710-47140	DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR , RH	1.00	\$996.60	25.00	\$747.45	Replace	nn X
		67003-47211	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	D. 3 ✓
			STICKER LOGO (RR DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	nu ✓
		62331-47050	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	1.00	\$317.10	25.00	\$237.83	Replace	? ✓

SMRT Accident Vehicle Repair Estimates

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67917-47070-C0	PLATE, REAR DOOR SCUFF, RH	1.00	\$123.00	25.00	\$92.25	Replace	?
		62551-47020-C0	GARNISH, REAR SEAT SIDE, RH	1.00	\$261.60	25.00	\$196.20	Replace	?
		67871-47051	WEATHERSTRIP, REAR DOOR RH	1.00	\$194.60	25.00	\$145.95	Replace	?
		69211-47021-A1	DOOR OUTER HANDLE REAR, RH	1.00	\$105.50	25.00	\$79.13	Replace	n 1 X
		69410-20110	DOOR LOOK STRIKER	1.00	\$42.60	25.00	\$31.95	Replace	17 X
		69050-52250	DOOR LOCK REAR, RH	1.00	\$607.90	25.00	\$455.92	Replace	Dupe/1M ✓
		68750-20122	HINGE ASSY, REAR DOOR, UPPER RH	1.00	\$107.00	25.00	\$80.25	Replace	Buy ✓
		68770-52031	HINGE ASSY, REAR DOOR, LOWER RH	1.00	\$93.90	25.00	\$70.43	Replace	Buy ✓
		68630-47050	CHECK ASSY, REAR DOOR	1.00	\$199.40	25.00	\$149.55	Replace	. ?
		85720-47150	DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR, RH	1.00	\$996.60	25.00	\$747.45	Replace	?
		69803-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	1.00	\$223.50	25.00	\$167.63	Replace	?
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace	DIS/CRG ✓
		65637-47060	LINER, REAR FENDER, RH	1.00	\$151.10	25.00	\$113.32	Replace	17 X
		75850-47910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	25.00	\$486.83	Replace	7011 ✓
Total					\$11,303.50		\$8,507.65		

Added Spare Parts / Material Usage After Surveyor Signed off

[illegible]