

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/TC, 24120330/4923

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SH13 59257at Workshop m/s SMART

of _____

Insured: SHC 86745

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

136916

Vehicle: IN / OUT

Date: _____ Person Contacted: 21452550Veh No: SH13 59257Yr Regn: 01/11/20Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (A)Make: Toyota Prius c.c. 1798Colour: maroon A/C: Insured / Std / NI / NASp. Reading: 442740 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU 703091705Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: green tree

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or beary wayFront 6Rear 6R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 19/12/24D.O.I. 23/12/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orU/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/1/25 be und 30-11-2024
 4/5 \$ 5050 inland 20h sun. (Red \$10175.50, 67%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 09/11/24

☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 5050)

SMRT Accident Vehicle Repair Estimates

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for a resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

no f Authorised
meray
23/12/24
h/s \$5050
5 days.
uly, he ARMY

SMRT Autor
60 Woodland
FAX Number
Estimator Te
Accident Rep
Date Genera
User ID

FCI

Acknowledged by Repairer

Section A - Accident Details

Registration Number	SHB5925T
Case Reference Number	TAX/12/24/2065
Registration Date	1/12/2020
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAN CHIN HIANG
Type of Accident	Head To Side
Accident Date and Time	19/12/2024 11:23 PM
Accident Reported Date and Time	20/12/2024 9:53 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24120056
Special Instruction to ARC, if any	DAMAGE TO THE RIGHT SIDE OF TAXI TOWED IN
Prepared Date and Time	20/12/2024 10:10 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$0.00
Total Spray Cost	\$1,794.00	\$0.00
Total Spare Part Cost	\$6,416.66	\$0.00
Total Other Cost	\$776.00	\$0.00
TOTAL COST	\$10,338.66	\$0.00
Lump Sum Total	\$10,350.00	\$0.00
Number of Repair Days	8.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	20/12/2024 10:30 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicab
TO REPAIR RH PORTION	\$1,352.00	200
Total Labour	\$1,352.00	800

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO RESPRAY FRONT DOOR RH	\$378.00	200
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	100
TO RESPRAY RH REAR DOOR	\$378.00	200
TO RESPRAY CENTRE PILLAR RH	\$220.00	100
TO RESPRAY REAR FENDER RH	\$378.00	200
TO RESPRAY DOOR HANDLE	\$220.00	50
Total Spray Painting & Panel Beating	\$1,794.00	850

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TOWING CHARGE	\$56.00	3.11 X
TO WASH AND VACUUM	\$60.00	1.1 X
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	20
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	60
TO TRANSFER DOOR MECHANISM	\$240.00	1.20
TO REPLACE SUNDRY PARTS	\$100.00	1.1 X
Total Other Costs	\$776.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	hob 6.00 ✓
			STICKER LOGO (FRT DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	SW ✓
		61311-47050	PILLAR, CENTER BODY, OUTER RH	1.00	\$349.50	25.00	\$262.13	Replace	R X
		68610-47040	CHECK ASSY, FRONT DOOR	1.00	\$199.40	25.00	\$149.55	Replace	nn X
		67861-47060	WEATHERSTRIP, FRONT DOOR RH	1.00	\$250.70	25.00	\$188.02	Replace	nn X
		69030-47100	LOCK ASSY, FRONT DOOR RH	1.00	\$655.30	25.00	\$491.47	Replace	nn X
		69210-47041-A1	DOOR OUTER HANDLE FRONT, RH	1.00	\$423.20	25.00	\$317.40	Replace	R X
		68710-12151	HINGE UPPER RHF, DOOR	1.00	\$105.50	25.00	\$79.13	Replace	nn X
		68730-12120	HINGE LOWER RHF, DOOR	1.00	\$120.00	25.00	\$90.00	Replace	nn X
		69801-21020	DOOR FRONT WINDOW REGULATOR SUB-ASSY, RH	1.00	\$257.80	25.00	\$193.35	Replace	nn X
		85710-47140	DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR, RH	1.00	\$996.60	25.00	\$747.45	Replace	nn X
		67003-47211	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	Dis ✓
			STICKER LOGO (RR DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	SW ✓
		62331-47050	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	1.00	\$317.10	25.00	\$237.83	Replace	nn X

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Generz

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		67917-47070-C0	PLATE, REAR DOOR SCUFF, RH	1.00 X	\$123.00	25.00	\$92.25	Replace	RHX
		62551-47020-C0	GARNISH, REAR SEAT SIDE, RH	1.00 X	\$261.60	25.00	\$196.20	Replace	RHX
		67871-47051	WEATHERSTRIP, REAR DOOR RH	1.00 X	\$194.60	25.00	\$145.95	Replace	RHX
		69211-47021-A1	DOOR OUTER HANDLE REAR, RH	1.00 X	\$105.50	25.00	\$79.13	Replace	n 1 X
		69410-20110	DOOR LOCK STRIKER	1.00 X	\$42.60	25.00	\$31.95	Replace	12 X
		69050-52250	DOOR LOCK REAR, RH	1.00	\$607.90	25.00	\$455.92	Replace	Dmg/KM ✓
		68750-20122	HINGE ASSY, REAR DOOR, UPPER RH	1.00	\$107.00	25.00	\$80.25	Replace	Buy ✓
		68770-52031	HINGE ASSY, REAR DOOR, LOWER RH	1.00	\$93.90	25.00	\$70.43	Replace	Buy ✓
		68630-47050	CHECK ASSY, REAR DOOR	1.00 X	\$199.40	25.00	\$149.55	Replace	n X
		85720-47150	DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR, RH	1.00	\$996.60	25.00	\$747.45	Replace	12 X
		69803-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	1.00	\$223.50	25.00	\$167.63	Replace	12 X
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace	DIS/CRG ✓
		65637-47060	LINER, REAR FENDER, RH	1.00 X	\$151.10	25.00	\$113.32	Replace	12 X
		75850-47910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	25.00	\$486.83	Replace	700 ✓
Total					\$11,303.50		\$8,507.65		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Ct
Total									

P- 5210.5
 252
 3907.87
 + 120
 4027.87
 - 1055.20Z
 3222.3
 1860
 5072.3

Section A - Accident Details

Registration Number	SHB5925T
Case Reference Number	TAX/12/24/2065
Registration Date	1/Dec/2020
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAN CHIN HIANG
Type of Accident	Head To Side
Accident Date and Time	19/Dec/2024 11:23 PM
Accident Reported Date and Time	20/Dec/2024 9:53 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24120056
Special Instruction to ARC, if any	DAMAGE TO THE RIGHT SIDE OF TAXI TOWED IN
Prepared Date and Time	20/Dec/2024 10:10 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$800.00
Total Spray Cost	\$1,794.00	\$850.00
Total Spare Part Cost	\$6,806.12	\$3,222.31
Total Other Cost	\$776.00	\$200.00
TOTAL COST	\$10,728.12	\$5,072.31
Lump Sum Total	\$10,750.00	\$5,050.00 (L/S)
Number of Repair Days	8.0	5.0
Prepared / Adjusted By	Boon Chew Tay	MARCUS CHUA (LKK) / FCI
ARC / Surveyor Sign Off Date	23/12/2024 4:20 PM	23/12/2024 12:48 PM
Signature		Marcus Chua
Remarks	Expected length of repair (days) = 5 days Expected release date of vehicle after repair (Subject to approval from FM and without Supplementary) = 31-12-2024 REQ TOWING INVOICE L/S REPAIR / AFTER PAINT PHOTO. FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR MARCUS CHUA (LKK) / HP : 9009 6608 / Email : marcuschua@lkkauto.com	

✓ o/c
9/1/25
1/5 \$5050

Section C - Quotation and Accident Invoice Details

Quotation Number	E24120185	Invoice Number	
Quotation Date	20/12/2024	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,352.00	\$800.00
Total Labour	\$1,352.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	\$100.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY CENTRE PILLAR RH	\$220.00	\$100.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY DOOR HANDLE	\$220.00	\$50.00
Total Spray Painting & Panel Beating	\$1,794.00	\$850.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$120.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$776.00	\$200.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		75850-47910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	25.00	\$486.83	Replace	Replace
		65637-47060	LINER, REAR FENDER, RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace	Replace
		69803-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	0.00	\$223.50	0.00	\$0.00	Replace	Check
		85720-47150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Check
		68630-47050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Check

✓
X
✓
X
X
X
X

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/01/2025
User ID : PohSuan

	68770-52031	HINGE ASSY, REAR DOOR , LOWER RH	1.00	\$93.90	25.00	\$70.43	Replace	Replace	√
	68750-20122	HINGE ASSY, REAR DOOR , UPPER RH	1.00	\$107.00	25.00	\$80.25	Replace	Replace	√
	69050-52250	DOOR LOCK REAR , RH	1.00	\$607.90	25.00	\$455.92	Replace	Replace	√
	69410-20110	DOOR LOCK STRIKER	0.00	\$42.60	0.00	\$0.00	Replace	Not Given	X
	69211-47021-A1	DOOR OUTER HANDLE REAR , RH	0.00	\$105.50	0.00	\$0.00	Replace	Not Given	X
	67871-47051	WEATHERSTRIP, REAR DOOR RH	0.00	\$194.60	0.00	\$0.00	Replace	Check	X
	62551-47020-C0	GARNISH, REAR SEAT SIDE, RH	0.00	\$261.60	0.00	\$0.00	Replace	Check	X
	67917-47070-C0	PLATE, REAR DOOR SCUFF, RH	0.00	\$123.00	0.00	\$0.00	Replace	Check	X
	62331-47050	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	0.00	\$317.10	0.00	\$0.00	Replace	Check	X
		STICKER LOGO (RR DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
	67003-47211	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	Replace	√
	85710-47140	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given	X
	69801-21020	DOOR FRONT WINDOW REGULATOR SUB-ASSY, RH	0.00	\$257.80	0.00	\$0.00	Replace	Not Given	X
	68730-12120	HINGE LOWER RHF, DOOR	0.00	\$120.00	0.00	\$0.00	Replace	Not Given	X
	68710-12151	HINGE UPPER RHF, DOOR	0.00	\$105.50	0.00	\$0.00	Replace	Not Given	X
	69210-47041-A1	DOOR OUTER HANDLE FRONT , RH	1.00	\$423.20	100.00	\$0.00	Replace	Repair	R
	69030-47100	LOCK ASSY, FRONT DOOR RH	0.00	\$655.30	0.00	\$0.00	Replace	Not Given	X
	67861-47060	WEATHERSTRIP, FRONT DOOR RH	0.00	\$250.70	0.00	\$0.00	Replace	Not Given	X
	68610-47040	CHECK ASSY, FRONT DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X
	61311-47050	PILLAR, CENTER BODY, OUTER RH	1.00	\$349.50	100.00	\$0.00	Replace	Repair	R
		STICKER LOGO (FRT DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
	67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	Replace	√
Total				\$11,303.50		\$4,027.89			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	4,027.89	
	-20%	
	3222.31	L/S \$5,050/-
+	800.00	
+	1050.00	
	5,072.31	

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB5925T
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Dec 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Maroon
Manufacturing Year:	2020
Engine No.:	2ZR2G87272
Chassis No.:	JTDKB3FU703091765
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	01 Dec 2020
First Registration Date:	01 Dec 2020
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Nov 2028
PARF Rebate Amount:	\$10,897.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$29,843.00
COE Rebate Amount:	\$14,683.00
Total Rebate Amount:	\$25,580.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Dec 2024

OK