



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL  50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 ATTN: AGNES CHAN			Ref: CS/SMO24120332/Uvp3m4 (N)  Date: 03/01/2025  Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	YN 4178A	<b>Veh. Inspected</b>	SDR 2088S
	<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	CMTD2403633/AGC	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	12/11/2024
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	SUZUKI SWIFT (A)	<b>c.c</b>	998
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
	<b>Chassis No.</b>	JSAAZC13S00305384	<b>Colour</b>	WHITE
	<b>Odometer</b>	43795 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	185/55R16	YOKOHAMA	6 mm
	<b>L/H Front Tyre</b>	185/55R16	YOKOHAMA	6 mm
	<b>R/H Rear Tyre</b>	185/55R16	YOKOHAMA	6 mm
	<b>L/H Rear Tyre</b>	185/55R16	YOKOHAMA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	11/11/2024	<b>Inspection Date</b>	13/11/2024
	<b>Survey held at</b>	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>15 Working Days</b>	