

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

11-12-24

Date Of Accident : 11-11-2024

OUR REF : SDR 2088S/T/24

Wong Yoke Peng

Blk 408 Jurong West St 42

#02-665

Singapore 640408

Attn: Mr. Marcus

Date in/out : 11/11/24 to 29/11/24

Acknowledged by Repairer

Signature:

Date:

ESTIMATE BILL ON VEH. NO. : SDR 2088S

MODEL : SUZUKI SWIFT

CHASSIS NO : JSAAZC13S00305384

LIST ITEM

Rear Bumper Fascia	810.75	DIS	911.05	✓
Rear Bumper Side Retainer	2pcs @ 25.00	But	50.00	✓
Rear Bumper Inner Side Dust Cover RH & LH	2pcs @ 55.10	to be	110.20	✓
Rear Bumper Lower Center Garnish		DIS	39.85	✓
Rear Bumper Clips	10pcs @ 5.00	ALL	50.00	30 S/N
Rear Number Plate Lamp	2pcs @ 42.00	11	84.00	X
Rear End Panel		30/1600	316.75	✓
Rear End Panel Top Trim		111	91.15	✓
Rear End Panel Top Trim Clips	4pcs @ 5.00	11	20.00	X
Rear End Panel Air Vent	2pcs @ 39.10	to be	78.20	✓
Tail Lamp Assy RH & LH	820 x 2 = 1640	CR	1,918.60	✓
Tail Lamp Clips	4pcs @ 5.00	11	20.00	X
Tail Lamp Base Panel RH & LH	2pcs @ 89.10	20/200	178.20	✓
Tail Gate		Body, 20	983.45	✓
Tail Gate Hinge RH & LH	2pcs @ 54.55	11	109.10	X
Tail Gate Stopper RH & LH	2pcs @ 20.00	11	40.00	X
Tail Gate Absorber	2pcs @ 126.10	11	252.20	X
Tail Gate Lock		111	89.30	✓
Tail Gate Lock Sticker		11	32.00	X

4387-88

Tail Gate Weatherstripe		7w1	85.10	/
Tail Gate Inner Trim Board		De/7w1	251.00	/
Tail Gate Inner Trim Board Clips	8pcs @ 5.00	nee	40.00	305/W
Tail Gate Badge		nee	27.10	/
Tail Gate Emblum "Swift"		nee	28.05	/
Tail Gate Emblum "Suzuki"		nee	27.20	/
Tail Gate Outer Opener Switch		Dange	120.10	/
Tail Gate Outer Keyless Antenna		one	76.65	/
Rear Floor Panel		crumpled/buc	381.86	/
Rear Floor Panel Insulator Cloth		NF	160.05	X
Rear Floor Panel Board		warped/bon	191.00	/
Rear fender inner trim boards	320422640 2pcs @ 573.10	De/D/S	1,146.20	/
Rear Windscreen Glass Moulding		nee	76.05	/
Rear Windscreen Glass Inner Seal		nee	50.00	/
Rear Windscreen Glass Clips	14pcs @ 5.00	nee	70.00	X
Front Bumper Fascia	820.15	Dis	911.05	/
Front Bumper Side Retainer	2pcs @ 28.00	N/S CNO	56.00	h c
Front Bumper Reinforcement		BMT	172.20	/
Front Bumper Tow Cover		7w1	37.15	/
Front Bumper Lower Center Grille Garnish		7w1 / CAT	120.05	/
Front Bumper Clips	10pcs @ 5.00	nee	50.00	305/W
Front Bumper Lower Support Garnish		7w1	72.40	/
Front Bumper Inner Air Grille Garnish (Top)		7w1	70.05	/
Front Grille		Cu7	283.00	/
Front Grille Badge		h 1	45.05	X
Front Bumper Inner Air Grille Garnish (Bottom)		7w1	38.15	/
Bonnet		7D/buc	705.90	/
Bonnet Hinge	2pcs @ 99.55	h	199.10	X
Bonnet Rubber Beading		nee	45.25	/

Bonnet Stopper	2pcs @ 15.00	11	30.00	X
Bonnet Insulator Clips	8pcs @ 5.00	11	40.00	X
Bonnet Lock		twl	89.30	/
Head Lamp Assy RH & LH	2pcs @ 2,093.60	one	4,187.20	/
Head Lamp Lower Bracket	2pcs @ 28.00	NS	56.00	X
Front Support "Center Top"		3uf	322.80	/
Front Support Side Brace Panel RH & LH	2pcs @ 45.80	NS 3uf	91.60	wc
Front Fender LH		3uc	389.15	/
Front Fender Inner Bracket		11	20.00	X
Front Fender Splash Shield		twl	129.15	/
Air Con Condensor		3uf/2u1	579.20	/
Air Con Condensor Mounting (Top)	2pcs @ 20.10	twl	40.20	/
Air Con Condensor Mounting (Bottom)	2pcs @ 20.10	11	40.20	X
Air Con Suction Pipe		11	167.13	X
Radiator Assy		980 3uf/2u1	1,007.30	/
Radiator Lower Mounting	2pcs @ 20.10	11	40.20	X
Radiator Top Mounting	2pcs @ 20.10	11	40.20	X
Radiator Fan Motor		3m	385.25	/
Radiator Fan Blade		su	90.50	X
Radiator Fan Cowling		cu	159.90	/
Turbo Inter Cooler		pu1	862.80	/
Turbo Inter Cooler Mounting "Top"		11	40.45	X
Turbo Inter Cooler Air Grille Garnish		twl	76.13	/
Front Fender Splash Shield Clips	6pcs @ 5.00	u1	30.00	/
Turbo Charger Heater Shield		3uf	85.15	/
Turbo Charger Water Pipe		su	68.50	X
Turbo Charger Water Hose		su	55.25	X
Turbo Charger Blow Off Valve		11	213.60	X
Fog Lamp LH		cu	220.35	/

Fog Lamp Cover

Dis 48.15 ✓

Horn Assy

11 76.35 X

20,591.77

Less Discount 15%: 3,088.77

17,503.00

SPECIAL NETT ITEM

Rear Number Plate

sent 45.00 } 40 s/n
29.00

Rear Number Plate Casing

1 set Reverse Sensor With Control Unit

malfunction 380.00 200 s/n

Rear Windscreen Glass Sealant

11 60.00 40 s/n

Front Number Plate

sent 45.00 } 40 s/n
29.00

Front Number Plate Casing

LABOUR CHARGE

To check wiring system

80.00 30

To reset electrical module system

280.00 50

To tuff coat affected areas

280.00 100

To remove & refix reverse sensor

120.00 30

To remove & refix rear windscreen glass

180.00 120

To remove & refix tail gate mechanism

220.00 60

To remove & refix air con condensor, piping, vacuum & top up gas

280.00 100

To remove & refix radiator, fan & top up coolant

200.00

To remove & refix turbo inter cooler, turbo blow off valve, heater shield and turbo by pass hose

280.00 50

To respray affected areas

1,800.00 ✓

To check & adjust chassis alignment on car O liner

11 380.00 X

To check & adjust computer wheel alignment

120.00 60

To renew damaged parts, straighten & repair rear RH & LH fender, front & rear chassis member, front LH wheel housing panel, front LH door & aligned all parts

1,800.00 ✓

24,231.00

GST 9%: 2,180.79

AMOUNT DUE: 26,411.79

2-1736479
152
14760.08
320
4200