

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

19-01-25

Date Of Accident : 18-12-2024

OUR REF : YR 2926A/T/24

ADF Waterproof Pte Ltd

25 Mandai Estate

#05-12 Innovation Place Tower 1

Singapore 729930

LKK Auto Consultants hence notify
the Repairer of the following
• To resurvey before/after spray painting
• To display damaged parts for resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Attn: Marcus

Date in/out : 18/12/24 to 26/12/24

*PART BY PART REPAIR

ESTIMATE BILL ON VEH. NO. : YR 2926A

VEH. MODEL : HINO XZU710R

CHASSIS NO. : JHHUCV3F70K057450

LIST ITEM

Tail Lamp Assy RH

CR 390.00

390.00

Less Discount 10% :

39.00

351.00

SPECIAL NETT ITEM

Rear Bumper Assy

DUS 1,500.00 800

Rear Step Bracket With Aluminium Plate

DUS 900.00 300

Rear Number Plate

Best 45.00 20

LABOUR CHARGE

To tuff coat affected areas

11 150.00 X

To check wiring system

50.00 20

To respray affected areas

700.00 400

To renew damaged parts, straighten & repair rear tail gate lower member,
rear RH & LH chassis member & aligned all parts

800.00 600

To remove & repair spare tyre carrier check function

11 120.00 X

4,616.00

GST 9%: 415.44

TOTAL AMOUNT: 5,031.44