

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: <u>SNM24D207160</u> Date: <u>26th Dec 2024</u>

Our Ref: <u>CS/CTI24120334/Knh3</u>

The Motor Claims Department China Taiping Insurance (S) Pte Ltd

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SNE 4441S .

We thank you for the instruction on 23/12/2024.

Please be informed that we had conducted the inspection of the abovementioned vehicle on <u>23/12/2024</u> at the premises of M/s <u>DING AUTO PTE LTD</u> and have the following to report:-

| Workshop Estimate Amount | : <u>S\$</u> | 94,008.21 . |
|--------------------------|---------------|--------------|
| Revised Estimate Amount | : <u>S\$</u> | 46,173.21 . |
| "Check" Items Amount | : <u>S\$</u> | 38,945.00 . |
| Total Amount | : <u>S\$</u> | 85,118.21 . |
| Market Value | : <u>S\$</u> | 137,000.00 . |
| LTA Reimbursement Value | : <u>S</u> \$ | 62,341.00 . |
| Nett Value | : <u>S</u> \$ | 74,659.00 . |

Description of Damage:

The vehicle sustained damages at the

front portion, o/s and n/s body.

The undercarriage affected due to collision.



Comments/ Present Status:

Suggest to do investigation for frt windscreen tinted film.

Repairer willing to undertake the repair cost not more than \$60,000.00 on lump sum basis.

Recommend days of repair: 22 days.

We have NOT authorise repair.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.

Yours faithfully

Kenneth Kong Licensed Appraiser