

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 24 Dec 2024

### **Preliminary Advice**

Insured Vehicle No : YP5762X  
TP Vehicle No : SNM4751E  
Make :  
Date of Inspection : 23/12/2024  
Inspection At : MY CAR CONSULTANT PTE LTD ( JALAN LAM HUAT ) (HQ)  
60 JALAN LAM HUAT #05-67/68, CARROS CENTRE  
SINGAPORE 737869

Accident Date : 19/12/2024  
Assignment Date : 23/12/2024  
Est. Duration of Repair : 5

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,596.00
Revised Amount	:S\$	6,603.75
Check Items (Estimated)	:S\$	1,207.50
Total	:S\$	7,811.25
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is economical for repair
  - ( ) The vehicle is not economical for repair
  - ( ) Part-by-Part repair
  - ( X ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.