

Not Authored
L1 Sup \$3250/h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7763E

AAD2403-104

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

02 JUL 2024

SHB7763E

JTDCB3FU503079646

200303878K

TOYOTA

PRIUS

24/3/2024

SHB3818H/FCI

29/3/2019

PART

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, REAR FLOOR
- 1 WHEEL, DISC
- 1 CAP, WHEEL
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 LENS AND BODY, REAR LAMP, RH (LOWER)
- 1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)
- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 LINER, REAR WHEEL HOUSE, RH

LIST

\$	Per	558.39	X
\$	in	19.43	X
\$	W/L	726.92	
\$	n	419.90	X
\$	in	155.72	X
\$	in	304.92	X
\$	in	220.50	X
\$	in	290.43	X
\$	in	2,554.70	X
\$	in	266.91	X
\$	n	824.46	X
\$	in	81.48	X
\$	CM	634.73	
\$	CM	570.15	
\$	Per	1,099.46	
\$	CM	176.09	
TOTAL	\$	8,728.07	
25%	\$	2,182.02	
	\$	6,546.05	

Special Nett

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 FENDER LINER CLIP
- 1 TYRE
- 1 END PANEL INNER TRIM CLIP
- 2 WINDSCREEN SEALANT

\$	in	700.00	X
\$	me	65.00	boja
\$	na	65.00	X
\$	in	300.00	X
\$	na	60.00	X
\$	na	150.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2403-104

SHB7763E

- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	<i>nn</i>	200.00	X
\$	<i>nn</i>	130.00	λ
TOTAL	\$	970.00	

TOTAL PARTS	\$	8,543.40
--------------------	----	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	<i>300</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	<i>4400</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>1000</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>200</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>6000</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
TOTAL	\$	5,990.00	

Over All Total	\$	21,079.45
-----------------------	----	------------------

(PART-BY-PART) Repair Days*07 Days**4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: