

(08/11/13) wef

REF:

CS/CT124120339/4vh3e2

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF 6803

at Workshop m/s Trans Eureka's P.30

of _____

Insured: 1/92493L

Policy No. _____

Claims No. SNM24D207148


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$53k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 76fc Vehicle: IN / OUT

174622655

Veh No: SMF 6803 Yr Regn: 17/10/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: Mazda CX-3 c.c. 1998

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 81891 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6DX2W7AK*0409/12

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 17/12/24 D.O.I. 30/12/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 11:50

10-4-28 Submit report. (reputable)

10/4/25 Submit preli report-revised fig \$6315.78 check items \$4548.02

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$) S + RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Report Format : _____

Lump Sum / I.B.I: (\$)

Survey Fee:

Transportation:

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	768C
Vehicle Details	
Vehicle No.:	SMF680B
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2024
Vehicle Make:	MAZDA
Vehicle Model:	CX-3 2.0 AT STANDARD 2WD
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	PE31287191
Chassis No.:	JM6DK2W7AK0409112
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$16,830.00
Original Registration Date:	12 Oct 2018
First Registration Date:	12 Oct 2018
Transfer Count:	1
Actual ARF Paid:	\$16,830.00 <i>4411</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Oct 2028
PARF Rebate Amount:	\$10,939.00
Intended COE Rebate Details	
COE Expiry Date:	11 Oct 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$31,001.00
COE Rebate Amount:	\$11,716.00
Total Rebate Amount:	\$22,655.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 30 Dec 2024

OK

Home>Used Cars>Listing

All Category

Search

Save Search


Any status 2018

Sort by Any Status, Date Posted (Newest)

Car MakePriceDepre2018MileageEng. CapOwner

19 Vehicles

Car Model

- 

Mazda CX-3 2.0A Standard

\$54,900

Instl. \$915 /mth

\$11,860 /yr

30-Nov-2018
(3yrs 10mths COE left)

N.A

1,998 cc

2 Owners

100% In-House/ Bank Loan Welcomed With Guaranteed Approval. \$0 Downpayment With Single Guarantor Immediate Approval Available. All Wears & Tears Rectified. STA/ Agent Pre-Purchase Inspection Welcomed. Proper In-House Aftersales Care Of 1-Year Warranty With 3 Complimentary Servicing On Engine, Gearbox & Electrical Components By M-Label Garage. Immediate Transfer Of Ownership. Contact Us Now!

M Label Auto Pte Ltd|Posted 28-Dec-2024

Compare
- 

Mazda CX-3 2.0A Standard

\$51,288

Instl. \$909 /mth

\$11,680 /yr

31-Aug-2018
(3yrs 8mths COE left)

63,000 km

1,998 cc

3 Owners

Superb condition, low mileage, CX-3 owned by super OCD work from home owner. Incredibly under-utilized. Engine/ATF oil servicing just done. Fantastic condition, super fuel efficient. Pristine paintwork, car grooming/polishing just done. Comes with 1 year engine and gearbox warranty for ultimate peace of mind. 3 FOC servicing to sweeten the deal. Consignment unit, viewing by appointment basis only.

Precision Automobile Pte Ltd|Posted 28-Dec-2024

Compare
- 

Mazda CX-3 2.0A Standard

\$45,389

Instl. \$973 /mth

\$11,720 /yr

16-Jan-2018
(3yrs COE left)

57,000 km

1,998 cc

Compare



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

CONTACT NO.: 6389 6111
MODEL: CX3IPM 2L CORE BLACK EURO6
CHASSIS NO.: JM6DK2W7AK0409112
ENGINE NO.: PE31287191
REG NO.: SMF680B
REGN DATE: 12/10/2018

PAGE NO.:
DOCUMENT NO.: 1659
DOCUMENT DATE: 20/12/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 24321
REF. NO.:
DATE IN:
EXT. WTY: 11/10/2023
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	CNTP TP CLAIM				0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER & TAILGATE. AND ALL ACCIDENT AFFECTED AREA.	792		1584	2,376.00	S
SUB	TO RESPRAY REAR BUMPER & TAILGATE.	756		1512?	2,835.00	S
SUB	TO TRANSFER REVERSE SENSORS.			180	330.00	S
SUB	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.				670.00	S
SUB	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.				120.00	S
SUB	TO SUPPLY NUMBER PLATE.			500	70.00	S
SUB	TO CARRY OUT BODY CAVITY PRESERVATION.				250.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			120	250.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			150	300.00	S
SUB	SUNDRIES.			20	50.00	S
DVY3-50-22X BBBUMPER, REA		1.00	1,431.78	*NO STOCK	1,431.78	S
B45A-56-146A FASTENER		10.00	2.36	*NO STOCK	23.60	S
BHN1-50-0Z1A GROMMET, SCREW		6.00	2.36	*NO STOCK	14.16	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts for reference
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 2
DOCUMENT NO.: 1659
DOCUMENT DATE: 20/12/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 24321
REF. NO.:
DATE IN:
EXT. WTY: 11/10/2023
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: CX3IPM 2L CORE BLACK EURO6
CHASSIS NO.: JM6DK2W7AK0409112
ENGINE NO.: PE31287191
REG NO.: SMF680B
REGN DATE: 12/10/2018

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross GST	
					amount	Code
			SGD		SGD	
BGV4-56-145	CLIP	6.00	2.36	*NO STOCK	14.16	S X
D10J-50-2J1B	RETAINER LHR BUMPER DK	1.00	28.49	*NO STOCK	28.49	S X
D10J-50-2H1B	RETAINER RHR BUMPER DK	1.00	28.49	*NO STOCK	28.49	S X
D10E-51-5M0A	REFLECTOR LHR REFLEX DK	1.00	189.14	*NO STOCK	189.14	S X
D10E-51-5L0	REFLECTOR RHR REFLEX- DK	1.00	189.14	*NO STOCK	189.14	S X
DK8A-50-371	GUARD LHR BUMPER DK	1.00	47.12	*NO STOCK	47.12	S 7
D10J-50-C51	COVER,UNDER-REAR DK	1.00	52.93	*NO STOCK	52.93	S 7
DH4J-50-350	SHIELD(L),SPLASH-R.B DK	1.00	99.96	*NO STOCK	99.96	S X
DH4J-50-340	SHIELD(R),SPLASH-R.B	1.00	96.09	*NO STOCK	96.09	S X
D10J-50-271	BRACKET(R),RR.BUMPER DK	2.00	29.08	*NO STOCK	58.16	S 7
D10J-50-1K5	PIN,LOCATOR	1.00	3.71	*NO STOCK	3.71	S 7
DB2P-50-260A	REINF.,REAR BUMPER DK	1.00	477.29	*NO STOCK	477.29	S 7
DB2R-51-150E	LAMP RHR COMB.DK	1.00	656.33	*NO STOCK	656.33	S X
DB2R-51-160E	LAMP LHR COMB.DK	1.00	656.33	*NO STOCK	656.33	S X
DB2R-51-3F0B	LAMP(R),TRUNK LID	1.00	348.10	*NO STOCK	348.10	S X
DB2R-51-3G0B	LAMP LH TRUNK LID DK	1.00	348.10	*EX-STOCK	348.10	S X
DB3D-51-3H8	GASKET(R), LAMP-TRUNK LID DK	1.00	53.94	*EX-STOCK	53.94	S 11
DB3D-51-3J8	GASKET(L), LAMP-TRUNK LID DK	1.00	53.94	*NO STOCK	53.94	S 11
DKY0-62-02XC	LIFT GATE DK	1.00	1,431.78	*NO STOCK	1,431.78	S 11
D10E-62-866A	COVER,HOLE DK	1.00	15.76		15.76	S 7

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 3
DOCUMENT NO.: 1659
DOCUMENT DATE: 20/12/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 24321
REF. NO.:
DATE IN:
EXT. WTY: 11/10/2023
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: CX3IPM 2L CORE BLACK EURO6
CHASSIS NO.: JM6DK2W7AK0409112
ENGINE NO.: PE31287191
REG NO.: SMF680B
REGN DATE: 12/10/2018

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
DM0P-68-960	TRIM,LIFTGATE-LOWER DK	1.00	303.85	*NO STOCK	303.85	S ?
D10E-62-761A	WEATHERSTRIP,LIFT GA DK	1.00	208.10	*NO STOCK	208.10	S ?
D24H-62-866	COVER,HOLE	4.00	2.36	STOCK	9.44	S ?
D10E-62-4B0B	SWITCH,OPEN LID GATE DK	1.00	113.36	*NO STOCK	113.36	S ?
D11B-51-730	MASCOT,REAR DK	1.00	70.88	*NO STOCK	70.88	S //
D10J-51-721	ORNAMENT,CAR NAME-RE DK	1.00	72.65	*NO STOCK	72.65	S //
D10J-51-771A	ORNAMENT DK	1.00	73.24	*EX-STOCK	73.24	S //
BF67-51-261	GROMMET	2.00	1.85	*NO STOCK	3.70	S //
EG21-51-SJ3	CLIP	2.00	5.56	*NO STOCK	11.12	S //
B01A-51-958	CLIP,SPOILER	3.00	2.95	*NO STOCK	8.85	S //
GB02-67-014	CLIP	1.00	3.37	*NO STOCK	3.37	S //
EG21-51-146	FASTENER	3.00	5.56	*NO STOCK	16.68	S //
B45A-51-2L0B	LHR LAMP LICENCE BM/DK	1.00	86.65	*NO STOCK	86.65	S ?
B45A-51-270B	RHR LAMP LICENSE BM/DK	1.00	86.65	*EX-STOCK	86.65	S ?
C513-50-896	FASTENER	2.00	7.42	*EX-STOCK	14.84	S //
D204-50-896A	FASTENER	2.00	2.36	*EX-STOCK	4.72	S //
GJ6A-50-897	SPACER	3.00	11.13	*NO STOCK	33.39	S //
FB01-63-959	TERMINAL,BACK WIND.	2.00	34.47	*NO STOCK	68.94	S //
G21E-63-938B	PIN,STUD	1.00	10.20		10.20	S //

		GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	7,519.13	O	-		-			
Surcharge	0.00	S	9.00%	14,770.13	1,329.31			
Labour	7,251.00							
Menus	0.00							
Gross						14,770.13	1,329.31	16,099.44
Less: Deposit**						0.00	0.00	0.00
Amount Due						14,770.13	1,329.31	16,099.44

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres:

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417