

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

0.5 days
 not Authorized
 in means
 24/1/24
 2/5 \$1600
 alypto Hb 97
 limited

VEHICLE NUMBER: JVX6772
 MAKE & MODEL: YAMAHA AEROX 155

FRONT RIM	su		\$850.00	X
FRONT RIM SHAFT	n1		\$90.00	X
FRONT FORK ASSY	but/au	640	\$881.20	/
FRONT FORK SIDE COVER L/R X2	n1		\$130.00	X
FRONT FORK UNDER BRACKET	but	185	\$350.00	/
STEERING CONE BEARING	rel	60	\$180.00	/
FRONT FENDER	320	140	\$240.00	/
HANDLE BAR	but	168	\$280.00	/
HANDLE BAR BALANCE SET	cut	40	\$110.00	/
HANDLE GRIP SET	n1		\$80.00	X
BRAKE HANDLE LEVER L/R X2	o/s cut	110	\$240.00	lpc
SIDE MIRROR SET	o/s cut	90	\$250.00	lpc
HEADLAMP	su		\$650.00	X
HEADLAMP STAY	n1		\$280.00	X
FRONT PANEL COVER	cut		\$180.00	/
FRONT PANEL INNER	cut		\$120.00	/
FRONT FAIRING COVER L/R X2	cut		\$500.00	/
FRONT FAIRING INNER L/R X2	o/s cut	80	\$160.00	lpc
FRONT FAIRING YAMAHA LOGO L/R X2	rel		\$90.00	/
FRONT SIGNAL LAMP L/R X2	n1/s su	85	\$240.00	lpc
FRONT FOOTREST BOARD L/R X2	cut	155x2=310	\$500.00	/
FRONT FOOTREST UNDER COVER L/R X2	cut		\$240.00	/
CENTRE COVER RH	su		\$140.00	X
REAR FOOTREST RH	su		\$120.00	X
EXHAUST COVER	cut	110	\$150.00	/
EXHAUST MUFFLER	R		\$895.00	X
RADIATOR COVER RH	cut		\$140.00	X
MAIN STAND	n1		\$250.00	X
REAR FENDER	su		\$150.00	X
REAR SIGNAL LAMP RH	n1		\$96.00	X
REAR FAIRING	cut	180	\$285.00	/
			\$8,867.20	
			Less 10%	\$886.72
				\$7,980.48
FRONT NUMBER PLATE	n1		\$45.00	X
COVERSET STICKER	rel		\$300.00	80
FRONT TYRE	n1		\$450.00	X
				\$795.00
TO CHECK ELECTRICAL WIRING	n1		\$50.00	X

TO REMOVE, REFIT AND REPLACE DAMAGE PARTS
TO SPRAY PAINT ON AFFECTED PANELS
TO REMOVE, REPLACE AND ALIGN FRONT FORK

	\$400.00	380
^^	\$300.00	X
^^	\$300.00	X
	<u>\$1,050.00</u>	

Total

\$9,825.48

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3288
102
299520
80
380
34882