



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref: CS/SMO24120342/Unp3e2
(N)

50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Date: 10/02/2025

ATTN: GNOH PAU LOONG

Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBK 1580D	Veh. Inspected	JVX 6772
Policy No.	D24MTPCVE000149	Coverage (\$)	0.00
Claim No.	CMTD2404017/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	23/12/2024

2. Vehicle Particulars & Condition

Make & Model	YAMAHA NVX 155	c.c	155
Engine No.	HIDDEN	Year of Reg.	2023
Chassis No.	PMYSG7420P0020201	Colour	GREY
Odometer	63665 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110-80-14	MAXXIS	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	140-70-14	MAXXIS	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, N/S AND O/S BODY. THE CHASSIS FRAME AFFECTED DUE TO COLLISION

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2024	Inspection Date	24/12/2024
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
--	-----------------------