

# Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
Tel : 64817221

*Not Authorized  
11 Sep @ 10,800h  
Mummy After Rain  
7 days*

Chua Lye Chye  
Blk 19 Joo Seng Road  
#02-116  
Singapore 360019

Vehicle No : SKR 3749 D  
Make : Toyota Altis  
Year : 2015

Qty	Description	Unit Price	Amount
<u>Estimate Cost Of Repair</u>			
1 pc	Rear boot lid	<i>Pr</i> \$965.50	✓
1 pc	Rear boot lid emblem - Altis	<i>Nr</i> \$75.10	✓
1 pc	Rear boot lid emblem - Corolla	<i>Nr</i> \$87.20	✓
1 pc	Rear boot lid emblem - Logo	<i>Nr</i> \$65.70	✓
1 pc	Rear boot lid outer chrome garnish	<i>Pr</i> \$287.60	X
1 pc	Rear boot lid inner lock	<i>Nr</i> \$385.70	✓
1 pc	Rear boot lid inner lock sensor	<i>CM</i> \$187.60	✓
1 pc	Rear boot rubber	<i>nd/br</i> \$225.60	50% ✓
2 pcs	Rear boot lid reflector	\$550.10	<i>Pr</i> \$1,100.20 X
2 pcs	Rear fender	\$1,149.20	<i>R</i> \$2,298.40 X
2 pcs	Rear fender innershield	\$125.10	<i>Pr</i> \$250.20 X
2 pcs	Rear fender inner trim	\$550.70	<i>Pr</i> \$1,101.40 X
1 pc	Rear end panel		<i>Pr</i> \$655.70 ✓
1 pc	Rear end panel inner garnish		<i>nr</i> \$263.70 ✓
2 pcs	Rear tail-lamp assy	\$625.60	<i>CM</i> \$1,251.20 ✓
2 pcs	Rear tail-lamp panel	\$255.10	<i>R</i> \$510.20 X
1 pc	Rear spare tyre panel		<i>R</i> \$1,150.60 X
1 pc	Rear spare tyre cover board		<i>CM</i> <del><i>CPA</i></del> \$455.60 <i>R</i> ✓
1 pc	Rear bumper		<i>Pr</i> \$654.80 ✓
1 pc	Rear bumper reinforcement		<i>Pr</i> \$487.60 ✓
2 pcs	Rear bumper bracket	\$155.10	<i>R</i> \$310.20 <i>R</i>
2 pcs	Rear bumper side retainer	\$85.10	<i>D/I</i> \$170.20 ✓
2 pcs	Rear bumper reflector	\$88.35	<i>Pr</i> \$176.70 X
1 set	Rear reverse sensor		<i>nd</i> \$395.10 <i>200% ✓</i>
1 pc	Rear exhaust silencer		<i>R</i> \$971.10 X
1 pc	Front bonnet		<i>R</i> \$950.60 X
1 pc	Front bonnet lock		<i>R</i> \$255.70 X
2 pcs	Front headlamp	\$3,933.10	<i>nr</i> \$7,866.20 ✓
1 pc	Front grille		<i>nr</i> \$753.20 <i>R</i>
1 pc	Front grille emblem		<i>nr</i> \$65.70 <i>R</i>
	balance c/f		\$24,374.30

*112-805N*

*e3604.30  
694.30*

*n/s m/c/m/s/m/c/m*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

SKR 3749 D

1 pc Front support panel  
 1 pc Front brace panel  
 1 pc Front bumper  
 1 pc Front bumper reinforcement  
 1 pc Front bumper sponge  
 1 pc Front bumper lower grille  
 1 pc Air con condenser

balance b/f \$24,374.30

R \$1,136.30 X  
 R \$125.60 X  
 CM \$659.30 ✓  
 R \$473.50 X  
 CM \$135.70 ✓  
 R \$225.60 X  
 R \$1,984.30 X  
 \$29,114.60

Less 25 % \$7,278.65  
 \$21,835.95

S Nett

1 pc Front no plate  
 1 pc Rear no plate  
 20 pcs Clip

RM \$40.00 ✓  
 R \$40.00 X  
 \$2.00 RM \$40.00 ✓  
 \$120.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,800.00 900

To putty & spray paint rear accident affected portion.

\$1,800.00 1200

Check/reconnect wiring.

\$45.00 40

To spray anti rust on accident affected portion.

\$180.00 60

Remove/renew rear exhaust silencer

RM \$180.00 X

Remove/refit rear boot upholstery to facilitate repair.

\$150.00 60

Remove/refit rear windscreen to facilitate repair

RM \$120.00 X

Remove/refit roof lining to facilitate repair.

RM \$180.00 X

Remove/renew air con condenser and to top up gas.

RM \$180.00 X

Total \$26,590.95