

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

*Not Authorized
11 Sep @ 10,800h
Mummy After Rain
7 days*

Chua Lye Chye
Blk 19 Joo Seng Road
#02-116
Singapore 360019

Vehicle No : SKR 3749 D
Make : Toyota Altis
Year : 2015

| Qty | Description | Unit Price | Amount |
|--------------------------------|------------------------------------|--|-------------|
| <u>Estimate Cost Of Repair</u> | | | |
| 1 pc | Rear boot lid | <i>Pr</i> \$965.50 | ✓ |
| 1 pc | Rear boot lid emblem - Altis | <i>Nr</i> \$75.10 | ✓ |
| 1 pc | Rear boot lid emblem - Corolla | <i>Nr</i> \$87.20 | ✓ |
| 1 pc | Rear boot lid emblem - Logo | <i>Nr</i> \$65.70 | ✓ |
| 1 pc | Rear boot lid outer chrome garnish | <i>Pr</i> \$287.60 | X |
| 1 pc | Rear boot lid inner lock | <i>Nr</i> \$385.70 | ✓ |
| 1 pc | Rear boot lid inner lock sensor | <i>CM</i> \$187.60 | ✓ |
| 1 pc | Rear boot rubber | <i>Nr/Pr</i> \$225.60 | 50% ✓ |
| 2 pcs | Rear boot lid reflector | \$550.10 | ✓ |
| 2 pcs | Rear fender | \$1,149.20 | X |
| 2 pcs | Rear fender innershield | \$125.10 | X |
| 2 pcs | Rear fender inner trim | \$550.70 | X |
| 1 pc | Rear end panel | <i>Pr</i> \$655.70 | ✓ |
| 1 pc | Rear end panel inner garnish | <i>Nr</i> \$263.70 | ✓ |
| 2 pcs | Rear tail-lamp assy | \$625.60 | ✓ |
| 2 pcs | Rear tail-lamp panel | \$255.10 | X |
| 1 pc | Rear spare tyre panel | <i>Nr</i> \$1,150.60 | X |
| 1 pc | Rear spare tyre cover board | <i>CM</i> <i>CPA</i> \$455.60 | ✓ |
| 1 pc | Rear bumper | <i>Pr</i> \$654.80 | ✓ |
| 1 pc | Rear bumper reinforcement | <i>Pr</i> \$487.60 | ✓ |
| 2 pcs | Rear bumper bracket | \$155.10 | X |
| 2 pcs | Rear bumper side retainer | \$85.10 | ✓ |
| 2 pcs | Rear bumper reflector | \$88.35 | X |
| 1 set | Rear reverse sensor | <i>Nr</i> \$395.10 | 200% ✓ |
| 1 pc | Rear exhaust silencer | <i>Nr</i> \$971.10 | X |
| 1 pc | Front bonnet | <i>Nr</i> \$950.60 | X |
| 1 pc | Front bonnet lock | <i>Nr</i> \$255.70 | X |
| 2 pcs | Front headlamp | \$3,933.10 | ✓ |
| 1 pc | Front grille | <i>Nr/Pr</i> \$753.20 | ✓ |
| 1 pc | Front grille emblem | <i>Nr</i> \$65.70 | ✓ |
| | balance c/f | | \$24,374.30 |

112-805N

*e3604.30
694.30*

n/s m/c/m/s/m/z cm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

SKR 3749 D

1 pc Front support panel
 1 pc Front brace panel
 1 pc Front bumper
 1 pc Front bumper reinforcement
 1 pc Front bumper sponge
 1 pc Front bumper lower grille
 1 pc Air con condenser

balance b/f \$24,374.30

R \$1,136.30 X
 R \$125.60 X
 CM \$659.30 ✓
 R \$473.50 X
 CM \$135.70 ✓
 R \$225.60 X
 R \$1,984.30 X
 \$29,114.60

Less 25 % \$7,278.65
 \$21,835.95

S Nett

1 pc Front no plate
 1 pc Rear no plate
 20 pcs Clip

RM \$40.00 ✓
 R \$40.00 X
 \$2.00 RM \$40.00 ✓
 \$120.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,800.00 900

To putty & spray paint rear accident affected portion.

\$1,800.00 1200

Check/reconnect wiring.

\$45.00 40

To spray anti rust on accident affected portion.

\$180.00 60

Remove/renew rear exhaust silencer

RM \$180.00 X

Remove/refit rear boot upholstery to facilitate repair.

\$150.00 60

Remove/refit rear windscreen to facilitate repair

RM \$120.00 X

Remove/refit roof lining to facilitate repair.

RM \$180.00 X

Remove/renew air con condenser and to top up gas.

RM \$180.00 X

Total \$26,590.95