

ASS. REC. BY:

REF: MS61

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/IV

To Inspect Vehicle No: _____

at Workshop n/s MASSIVE

of 259B

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$115K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

12/30

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKR 3749D Yr Regn: 02, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or SA

Make: Toy Altis c.c. 1598

Colour: M. Blue AC: Insured / Std / NI / NA

Sp. Reading: 364736 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO53REM104525895

Gen. Cohd: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STB A/Rlm or

Tyre Size: F: Mic 205/55R16

R: Nexen

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or

Front

Rear

R/Bal. 3 mm

R/Bal. 2 mm

L/Bal. 3 mm

L/Bal. 2 mm

D.O.A. 26/11/24

D.O.I. 24/12/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

& 151

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prell. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Transportation

_____ S - RS. _____ SI

_____ P. _____

_____ Others _____

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Chua Lye Chye
Blk 19 Joo Seng Road
#02-116
Singapore 360019

Vehicle No : SKR 3749 D
Make : Toyota Altis
Year : 2015

Not Authorized
1 Day &
Mummy After Rain
7 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid	<i>Pr</i>	\$965.50	✓
1 pc	Rear boot lid emblem - Altis	<i>Pr</i>	\$75.10	✓
1 pc	Rear boot lid emblem - Corolla	<i>Pr</i>	\$87.20	✓
1 pc	Rear boot lid emblem - Logo	<i>Pr</i>	\$65.70	✓
1 pc	Rear boot lid outer chrome garnish	<i>Pr</i>	\$287.60	X
1 pc	Rear boot lid inner lock	<i>Pr</i>	\$385.70	✓
1 pc	Rear boot lid inner lock sensor	<i>cm</i>	\$187.60	✓
1 pc	Rear boot rubber	<i>nd/br</i>	\$225.60	50% ✓
2 pcs	Rear boot lid reflector	<i>Pr</i>	\$550.10	\$1,100.20 X
2 pcs	Rear fender	<i>Pr</i>	\$1,149.20	\$2,298.40 X
2 pcs	Rear fender innershield	<i>Pr</i>	\$125.10	\$250.20 X
2 pcs	Rear fender inner trim	<i>Pr</i>	\$550.70	\$1,101.40 X
1 pc	Rear end panel	<i>Pr</i>	\$655.70	✓
1 pc	Rear end panel inner garnish	<i>mit</i>	\$263.70	✓
2 pcs	Rear tail-lamp assy	<i>cm</i>	\$625.60	\$1,251.20 ✓
2 pcs	Rear tail-lamp panel	<i>Pr</i>	\$255.10	\$510.20 X
1 pc	Rear spare tyre panel	<i>Pr</i>		\$1,150.60 X
1 pc	Rear spare tyre cover board	<i>Pr</i>		\$455.60 X?
1 pc	Rear bumper	<i>Pr</i>		\$654.80 ✓
1 pc	Rear bumper reinforcement	<i>Pr</i>		\$487.60 ✓
2 pcs	Rear bumper bracket		\$155.10	\$310.20 ?
2 pcs	Rear bumper side retainer		\$85.10	\$170.20 ✓
2 pcs	Rear bumper reflector	<i>Pr</i>	\$88.35	\$176.70 X
1 set	Rear reverse sensor	<i>nd</i>		\$395.10 200% X
1 pc	Rear exhaust silencer	<i>Pr</i>		\$971.10 X
1 pc	Front bonnet	<i>Pr</i>		\$950.60 X
1 pc	Front bonnet lock	<i>Pr</i>		\$255.70 X
2 pcs	Front headlamp	<i>n/s?</i>	\$3,933.10	\$7,866.20 ✓
1 pc	Front grille	<i>clsm3 cm</i>		\$753.20 ?
1 pc	Front grille emblem			\$65.70 ?
			balance c/f	\$24,374.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

SKR 3749 D

1 pc Front support panel
 1 pc Front brace panel
 1 pc Front bumper
 1 pc Front bumper reinforcement
 1 pc Front bumper sponge
 1 pc Front bumper lower grille
 1 pc Air con condenser

S Nett

1 pc Front no plate
 1 pc Rear no plate
 20 pcs Clip

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.
 To putty & spray paint rear accident affected portion.
 Check/reconnect wiring.
 To spray anti rust on accident affected portion.
 Remove/renew rear exhaust silencer
 Remove/refit rear boot upholstery to facilitate repair.
 Remove/refit rear windscreen to facilitate repair
 Remove/refit roof lining to facilitate repair.
 Remove/renew air con condenser and to top up gas.

balance b/f \$24,374.30

R \$1,136.30 X
R \$125.60 X
CM \$659.30 ✓
 \$473.50 ?
 \$135.70 ?
R \$225.60 X
R \$1,984.30 X

\$29,114.60
 Less 25 % \$7,278.65
 \$21,835.95

NU \$40.00 ✓
R \$40.00 X
 \$2.00 *NU* \$40.00 ✓
 \$120.00

\$1,800.00 *90d*
 \$1,800.00 *120d*
 \$45.00 *4d*
 \$180.00 *6d*
NU \$180.00 X
 \$150.00 *6d*
NU \$120.00 X
NU \$180.00 X
 \$180.00 ?
 Total \$26,590.95