

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Chua Lye Chye
Blk 19 Joo Seng Road
#02-116
Singapore 360019

Vehicle No : SKR 3749 D
Make : Toyota Altis
Year : 2015

*Not Authorized
Call No 10,800
Mummy Ate Rain
7 days*

Qty	Description	Unit Price	Amount
Estimate Cost Of Repair			
1 pc	Rear boot lid	R1 \$965.50	—
1 pc	Rear boot lid emblem - Altis	R1 \$75.10	—
1 pc	Rear boot lid emblem - Corolla	R1 \$87.20	—
1 pc	Rear boot lid emblem - Logo	R1 \$65.70	—
1 pc	Rear boot lid outer chrome garnish	R1 \$287.60	X
1 pc	Rear boot lid inner lock	R1 \$385.70	—
1 pc	Rear boot lid inner lock sensor	CM \$187.60	—
1 pc	Rear boot rubber	112.80 SN R1/R2 \$225.60	50 SN
2 pcs	Rear boot lid reflector	\$550.10 R1	\$1,100.20 X
2 pcs	Rear fender	\$1,149.20 R	\$2,298.40 X
2 pcs	Rear fender innershield	\$125.10 R	\$250.20 X
2 pcs	Rear fender inner trim	\$550.70 R	\$1,101.40 X
1 pc	Rear end panel	R1 \$655.70	—
1 pc	Rear end panel inner garnish	Mil \$263.70	—
2 pcs	Rear tail-lamp assy	\$625.60 CM	\$1,251.20 —
2 pcs	Rear tail-lamp panel	\$255.10 R	\$510.20 X
1 pc	Rear spare tyre panel	R \$1,150.60	X
1 pc	Rear spare tyre cover board	CM CPA \$455.60	R
1 pc	Rear bumper	R1 \$654.80	—
1 pc	Rear bumper reinforcement	R1 \$487.60	—
2 pcs	Rear bumper bracket	\$155.10 R	\$310.20 R
2 pcs	Rear bumper side retainer	\$85.10 D1	\$170.20 —
2 pcs	Rear bumper reflector	\$88.35 R	\$176.70 X
1 set	Rear reverse sensor	R1 \$395.10	200 SN
1 pc	Rear exhaust silencer	R \$971.10	X
1 pc	Front bonnet	R \$950.60	X
1 pc	Front bonnet lock	R \$255.70	X
2 pcs	Front headlamp	\$3,933.10 R	\$7,866.20 —
1 pc	Front grille	M3 CM \$753.20	R
1 pc	Front grille emblem	R1 \$65.70	R

*3604.30
694.30*

n/s m3 cm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

balance c/f \$24,374.30

SKR 3749 D

balance b/f \$24,374.30

1 pc	Front support panel
1 pc	Front brace panel
1 pc	Front bumper
1 pc	Front bumper reinforcement
1 pc	Front bumper sponge
1 pc	Front bumper lower grille
1 pc	Air con condenser

R	\$1,136.30	X
R	\$125.60	X
CM	\$659.30	✓
R	\$473.50	X
CM	\$135.70	✓
R	\$225.60	X
R	\$1,984.30	X
	<u>\$29,114.60</u>	
Less 25 %	\$7,278.65	
	<u>\$21,835.95</u>	

S Nett

1 pc	Front no plate
1 pc	Rear no plate
20 pcs	Clip

	\$40.00	✓
	\$40.00	X
\$2.00	\$40.00	✓
	<u>\$120.00</u>	

Labour Charges

- Remove/renew the above parts including knocking, welding & cutting.
- To putty & spray paint rear accident affected portion.
- Check/reconnect wiring.
- To spray anti rust on accident affected portion.
- Remove/renew rear exhaust silencer
- Remove/refit rear boot upholstery to facilitate repair.
- Remove/refit rear windscreen to facilitate repair
- Remove/refit roof lining to facilitate repair.
- Remove/renew air con condenser and to top up gas.

	\$1,800.00	900
	\$1,800.00	1200
	\$45.00	40
	\$180.00	60
RV	\$180.00	X
	\$150.00	60
RV	\$120.00	X
RV	\$180.00	X
RV	\$180.00	X
Total	<u>\$26,590.95</u>	