



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: EILEEN			Ref: CS/FCI24120345/Knp3e2(N) Date: 03/02/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 8283E	Veh. Inspected	SLF 6561J
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24011155MFCT	Excess (\$)	0.00
	Assign From	EILEEN	Assign Date	23/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MR053REH104554290	Colour	METALLIC SILVER
	Odometer	132583 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55Z R16	NEXEN	6 mm
	L/H Front Tyre	205/55Z R16	NEXEN	6 mm
	R/H Rear Tyre	205/55Z R16	NEXEN	4 mm
	L/H Rear Tyre	205/55Z R16	NEXEN	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/12/2024	Inspection Date	24/12/2024
	Survey held at	ESTEEM PERFORMANCE PTE LTD 176 SIN MING DRIVE #01-14 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	