

ASS. REC. BY:

REF:

PCZ1

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s

Esteeon

of

176

1510

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 229k

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 2-4 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLF 6561JYr Regn: 091 16Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota

c.c

1598

Colour: Dark Silver

AC:

Insured / Std / NI / NA

Sp. Reading: 132583

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053REH 104554290Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orMod: ☒ NII / S/Rim / STD / R/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

205/558R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal. 6 mmR/Bal. 4 mmL/Bal. 6 mmL/Bal. 4 mmD.O.A. 18/12/24D.O.I. 24/12/2024Survey held at ✓Des. of Damages: ☒ Fnt / Rear / O/S / N/S / UIC / Rooftop or

None N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐

: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

) \$ - RS. \$

), Fuel \$

), Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

MS-First  
Capital.

Pr-20/12@403.



**ESTEEM**

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

**Repair Estimates**

SLF 6561 J

|              |                             |           |                 |
|--------------|-----------------------------|-----------|-----------------|
| Parts        | (a) Cost / List Price Items | \$        | 8,387.07        |
|              | Plus/Less 25%               | \$        | 2,096.77        |
|              | <b>Total of Cost / List</b> | <b>\$</b> | <b>6,290.30</b> |
|              | (b) Nett Price Items        |           |                 |
|              | Less                        |           |                 |
|              | <b>Total of Nett Item</b>   |           |                 |
|              | (c) Special Nett Items      |           |                 |
|              | <b>Total Parts Cost</b>     |           |                 |
| Labour       |                             | \$        | 3,120.00        |
| <b>Total</b> |                             | <b>\$</b> | <b>9,410.30</b> |

Not Authorized  
1/Rep &  
Picking After Paint

The above total will be subjected to 9% G.S.T.

Name of Surveyor

Company

Survey conducted on

Hennem

LICK

28/12/24

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 2-4 day(s)

(c) Resurvey : Required / Not ~~Required~~

(d) Excess : \$

(e) Signature of surveyor

Date:

28/12/24

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

**Spare Parts**

Vehicle No. :  
Make & Model : **SLF6561J**  
Chassis No. : **TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT**  
**MR053REH104554290**

Submit By :  
Year Manufacture : **02-Sep-16**  
Engine No. : **1ZRY313612**  
**Cost / List**

| S/No. | Part Description             | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|------------------------------|-----|------------|-------|-------------------------|
| 1     | Reverse sensor               | 2   | \$252.20   |       | 20052                   |
| 2     | Rear bumper                  | 1   | \$855.40   |       | —                       |
| 3     | Rear bumper clip             | 10  | \$60.00    |       | —                       |
| 4     | Rear bumper side retainer LH | 1   | \$168.10   |       | —                       |
| 5     | Rear bumper side retainer RH | 1   | \$168.10   |       | X                       |
| 6     | Rear bumper bracket LH       | 1   | \$94.10    |       | 7                       |
| 7     | Rear bumper bracket RH       | 1   | \$94.10    |       | X                       |
| 8     | Rear bumper sponge           | 1   | NA         |       |                         |
| 9     | Rear bumper reinforcement    | 1   | \$615.60   |       | 7                       |
| 10    | Rear bumper reflector LH     | 1   | \$83.40    |       | X                       |
| 11    | Rear bumper reflector RH     | 1   | \$83.40    |       | X                       |
| 12    | Bootlid                      | 1   | \$1,218.30 |       | X                       |
| 13    | Bootlid lock                 | 1   | \$553.10   |       | X                       |
| 14    | Bootlid hinge LH             | 1   | \$96.30    |       | X                       |
| 15    | Bootlid hinge RH             | 1   | \$96.30    |       | X                       |
| 16    | Bootlid emblem               | 1   | \$61.70    |       | X                       |
| 17    | Wording "COROLLA"            | 1   | \$54.17    |       | X                       |
| 18    | Wording "ALTIS"              | 1   | \$51.60    |       | X                       |
| 19    | Bootlid reflector LH         | 1   | \$596.20   |       | X                       |
| 20    | Bootlid reflector RH         | 1   | \$596.20   |       | X                       |
| 21    | Tail end panel               | 1   | \$1,025.30 |       | 7                       |
| 22    | Tail end panel garnish       | 1   | \$334.70   |       | 7                       |
| 23    | Tail end panel garnish clip  | 10  | \$60.00    |       | 7                       |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge  
will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. :  
Make & Model :  
Chassis No. :

**SLF6561J**

TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT  
MR053REH104554290

Submit By :  
Year Manufacture :  
Engine No. :  
**Cost / List**

0  
42615

| S/No. | Part Description | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|------------------|-----|------------|-------|-------------------------|
| 24    | Tail lamp LH     | 1   | \$584.40   |       | X                       |
| 25    | Tail lamp RH     | 1   | \$584.40   |       | X                       |
| 26    |                  |     |            |       |                         |
| 27    |                  |     |            |       |                         |
| 28    |                  |     |            |       |                         |
| 29    |                  |     |            |       |                         |
| 30    |                  |     |            |       |                         |
| 31    |                  |     |            |       |                         |
| 32    |                  |     |            |       |                         |
| 33    |                  |     |            |       |                         |
| 34    |                  |     |            |       |                         |
| 35    |                  |     |            |       |                         |
| 36    |                  |     |            |       |                         |
| 37    |                  |     |            |       |                         |
| 38    |                  |     |            |       |                         |
| 39    |                  |     |            |       |                         |
| 40    |                  |     |            |       |                         |
| 41    |                  |     |            |       |                         |
| 42    |                  |     |            |       |                         |
| 43    |                  |     |            |       |                         |
| 44    |                  |     |            |       |                         |
| 45    |                  |     |            |       |                         |
| 46    |                  |     |            |       |                         |

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# ESTEEM

ESTEEM PERFORMANCE PTE LTD  
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP  
385 Sin Ming Drive  
Singapore 575718  
(T) 6753 2112 (F) 6451 0394

WORKSHOP  
176 Sin Ming Drive  
Sin Ming Auto Care #01-14, #01-15, #01-16  
Singapore 575721  
(T) 6484 1221 (F) 6484 7829

## Labour

Vehicle No. : **SLF6561J** Submit By : **0**  
Make & Model : **COROLLA ALTIS CLASSIC 1.6 C** Year of Manufacture : **42615**

| S/No | Labour Description                                                                                              | Estimated Price | Adjusted Price |
|------|-----------------------------------------------------------------------------------------------------------------|-----------------|----------------|
| 1    | TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,BOOTLID,END PANEL,LHR FENDER,RHR FENDER)   | \$1,200.00      | ?              |
| 2    | TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,BOOTLID,END PANEL,LHR FENDER,RHR FENDER) | \$1,200.00      | 4001           |
| 3    | To check wiring                                                                                                 | \$50.00         | 151            |
| 4    | To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.                                | \$150.00        | ?              |
| 5    | To tuff coat.                                                                                                   | \$100.00        | ?              |
| 6    | To transfer boot mechanism to new boot <i>nn</i>                                                                | \$150.00        | X              |
| 7    | To conduct water leakage tests to ensure proper air and sealing <i>nn</i>                                       | \$150.00        | X              |
| 8    | To remove & refit reverse sensor                                                                                | \$120.00        | 501            |
|      |                                                                                                                 |                 |                |
|      |                                                                                                                 |                 |                |
|      |                                                                                                                 |                 |                |
|      |                                                                                                                 |                 |                |
|      |                                                                                                                 |                 |                |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

|                                 |                                               |
|---------------------------------|-----------------------------------------------|
| Date of First Submission        | 19/12/2024 16:15 (SGT)                        |
| Reported by                     | Owner                                         |
| Date of Accident                | 18/12/2024 14:00 (SGT)                        |
| Exact Location of Accident      | Lor 4 Toa Payoh & Lor. 5 Toa Payoh, Singapore |
| Additional Location Information | Junction                                      |
| Country/State of Loss           | Singapore                                     |

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLF6561J

### INSURED/POLICYHOLDER

|                          |                             |
|--------------------------|-----------------------------|
| Is company?              | Yes                         |
| Name Of Registered Owner | GOLDBELL CAR RENTAL PTE LTD |
| Company Reg No           | 2XXXXX651D                  |
| Email Address            | accident@gbcr.com.sg        |
| Mobile Phone No          | (Phone) +65-66039398        |
| Alternative Phone No     | -                           |

### VEHICLE PARTICULARS

|                                                                              |                           |
|------------------------------------------------------------------------------|---------------------------|
| Manufacturer                                                                 | Toyota                    |
| Model                                                                        | Corolla                   |
| Variant                                                                      | -                         |
| Exact purpose for which vehicle was being used at time of accident           | Private use               |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category                                                             | Private car               |
| Transmission                                                                 | Auto                      |
| CC                                                                           | 1598                      |
| Vehicle Fuel                                                                 | -                         |
| First Registration Date                                                      | -                         |
| Chassis no                                                                   | -                         |
| Effective Date/Time of Ownership                                             | -                         |

### INSURANCE COMPANY

|                                   |                                      |
|-----------------------------------|--------------------------------------|
| Name of Insurance Company         | Tokio Marine Insurance Singapore Ltd |
| Policy Number / Cover Note Number | 24-MAB00157-R00                      |

DRIVER

# IMPORTANT NOTICE

## SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC card)

SOH JIT HOON  
Rec'd 19 DEC 2024

### Sketch Plan