



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

LONPAC INSURANCE BHD

DATE : 23-12-2024

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555

VEHICLE NO. : YN4584K

ACCIDENT DATE : 19-12-2024 18:35

THIRD PARTY REF. : SHC2554U

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE YN4584K MITSUBISHI

CANTER FEB21ER4SDEB

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT WINDSCREEN RUBBER X nn	280.00
2	2	FRONT CORNER PANEL@\$350.00 (LH) - BR (RH) X nn	700.00 350 /
3	1	FRONT WIPER PANEL / CRU	380.00 /
4	1	FRONT PANEL / DP	1000.00 /
5	1	FRONT PANEL FUSO EMBLEM / MC	100.00 /
6	1	FRONT GRILLE / MIS	680.00 /
7	1	FRONT GRILLE EMBLEM / MIS	65.00 /
8	1	FRONT GRILLE CANTER EMBLEM / MIS	65.00 /
9	1	FRONT GRILLE BRACKET / MIS	105.00 /
10	10	FRONT GRILLE CLIP@\$3.50 / MC	35.00 /
11	2	FRONT HEADLAMP@\$380.00 / BR	760.00 /
12	2	FRONT HEADLAMP LOWER RUBBER@\$35.00 X nn	70.00
13	2	FRONT SIGALLAMP@\$260.00 (LH) - BR (RH) X nn	520.00 260 /
14	2	FRONT SIDE LAMP@\$210.00 X nn	420.00
15	1	FRONT BUMPER / DP	750.00 /
16	2	FRONT BUMPER BRACKET@\$155.00 ? / BT	310.00 /
17	2	FRONT BUMPE SIDE RUBBER@\$280.00 (RH) / CRU (LH) / CRU	560.00 /
18	2	FRONT BUMPER INNER BRACKET@\$135.00 ? / BT	270.00 /
19	1	AIR CON BLOWER ? / BR	2350.00 /
20	1	HEATER UNIT ? / BR	750.00 /
21	1	RADIATOR ? x nn	980.00
22	1	RADIATOR FAN COWLING ? x nn	300.00
23	1	RADIATOR FAN ? x nn	320.00
24	1	RADIATOR FAN CLUCTH ? x nn	450.00
25	1	FRONT CABIN BAR ? / BT	650.00 /

Steve (LKK)

23/12/24, 4.45 pm

00-M AL

EXPI - ?

L/S

4 AL sy, 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : YN4584K
ACCIDENT DATE : 19-12-2024 18:35
THIRD PARTY REF. : SHC2554U

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
26	2	FRONT CABIN BAR SEAL@\$115.00 / TN	230.00 /
27	2	FRONT CABIN BAR BRACKET@\$450.00 / BT	900.00 /
28	1	HORN X nn	85.00
			14,085.00
ADD 20 %			2,817.00
TOTAL (A)			16,902.00

SPECIAL NETT ITEMS

1	1	FRONT NUMBER PLATE / BT	50.00 /
TOTAL (C)			50.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	50.00 30
2	1	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	100.00 /
3	1	TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS	180.00 150
4	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	1050.00 800
5	1	SPRAYPAINTING CHARGES	980.00 700
TOTAL (D)			2,360.00
ESTIMATE TOTAL			19,312.00