

# 國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.  
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177  
Email: ktmotorwerk@hotmail.com  
Reg. No.: S3373462B

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Vehicle Number :** SNP4222A  
**Vehicle Model :** HONDA STEPWAGON  
**Accident Date :** 19.12.2024  
**Original Reg Date :** 08.02.2024

**Date :** 06.01.2025  
**Signature:**  
**Chassis :** RP81047776  
**TP Ins. :** INCOME

## ESTIMATE

1	1 pc	REAR FENDER RH <i>Dented</i>	1,985.20	✓
2	1 pc	REAR FENDER INNER COWLING RH <i>new</i>	260.80	X
3	1 pc	REAR FENDER RAILWAY COVER GARNISH RH <i>new</i>	439.20	X
4	1 pc	REAR FENDER INNERTRIM RH <i>Not new</i>	798.10	X
5	1 pc	REAR TAILLAMP RH <i>ut</i>	944.30	650
6	1 pc	REAR BUMPER <i>Repr</i>	1,480.20	X
7	1 pc	REAR BUMPER SENSOR <i>new</i>	278.50	X
8	1 pc	REAR BUMPER RETAINER RH (FRONT) <i>new</i>	120.50	X
9	1 pc	REAR BUMPER RETAINER RH (REAR) <i>new</i>	155.30	X
10	1 pc	REAR BUMPER CHROME RH <i>new</i>	289.70	X
11	1 pc	REAR RIM RH <i>ut</i>	1,233.40	500 (sw)
12	1 pc	REAR WHEELHUB BEARING RH <i>Not new</i>	425.80	X
13	1 pc	REAR ABSORBER RH <i>Not new</i>	438.70	X

2635.20 LIST PRICE 8,849.70  
2108.16 Less 20% 1,769.94  
S.N. 500 TOTAL 7,079.76

### Special Nett

1	1 pc	Rear fender glass Sealant <i>new</i>	60.00	40
2	1 pc	Tyre <i>Not new</i>	350.00	X
3	1 set	Rear bumper clips <i>new</i>	30.00	X
4	1 set	Rear fender innercowling clips <i>Not new</i>	30.00	X

### Labour charge

Panel Beating	1,000.00	500
Spray painting	1,000.00	500
Anti rust	100.00	60
Remove and install fender glass	120.00	40 1160
To perform computerised wheel alignment	120.00	X
To perform computer reset and apdat	350.00	X
Remove and install interior uphostery	150.00	60
Remove and install reverse sensor	120.00	X

*total: 3808.16* \$ 10,509.76

*r/s: 3K*  
*04 Days* (3K)