

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

*not allowed
in
merc
24/12/24
1/5 @ 2400/
Weigh. Heavy
4 days*

31-01-25

Date Of Accident : 15-11-2024

Attn: Marcus

OUR REF : GY 5850R/T/24

Date in/out: 23/12/24 to 31/12/24

Casserole Catering Services Pte Ltd
17 Chin Bee Crescent
Singapore 619898

LKK Auto Consultants hence notify the Supplier of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Date:

ESTIMATE BILL ON VEH. NO. : GY 5850R

MODEL : TOYOTA DYNA Acknowledged by Repairer

CHASSIS NO : JTFUF34Y803010427

LIST ITEM

Front Door RH	<i>n.p/suf</i>	1,218.40
Front Door Hinge (Bottom)	<i>n</i>	131.70 X
Front Door Lower Step Garnish RH	<i>gross</i>	281.75
Front Door Weatherstripe	<i>n</i>	219.00 X
Front Bumper	<i>suf</i>	356.65
Head Lamp RH	<i>one</i>	789.10
		<hr/>
		2,996.60
	Less Discount 25%:	<hr/> 749.15
		<hr/> 2,247.45

SPECIAL NETT ITEM

Front Door R.O.C Sticker *new* 40.00 *30*

LABOUR CHARGE

To check wiring system 50.00 *20*

To remove & refix front RH door mechanism 250.00 *50*

To respray affected areas 600.00 *500.*

To renew damaged parts, straighten & repair and aligned all parts 600.00 *400*

3,787.45
GST 9% :

340.87

*P-2648-90
252
1984.42*