



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWERSINGAPORE 048583 ATTN: KAHARUDIN		Ref: CS/LIP24120352/Uvh3m4(N) Date: 13/02/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SNE 3A	Veh. Inspected	GY 5850R
Policy No.		Coverage (\$)	0.00
Claim No.	AVS24/3575	Excess (\$)	0.00
Assign From	KAHARUDIN	Assign Date	25/11/2024
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA (M)	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	JTFUF34Y803010427	Colour	WHITE
Odometer	842664 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185 R14	FALKEN	6 mm
L/H Front Tyre	185 R14	FALKEN	6 mm
R/H Rear Tyre	155 R12 (D)	FALKEN	6/6 mm
L/H Rear Tyre	155 R12 (D)	FALKEN	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/11/2024	Inspection Date	24/12/2024
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
5a. Remarks			
A)REGISTRATION DATE: 31 MAY 2005 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	