

**ACCIDENT INVOLVING SAF
GRADE 1 STAFF CAR (MID 35 /
SJR9174J) ALONG UPPER
BUKIT TIMAH RD (TOWARDS
WOODLANDS RD) ON 25 OCT
2024 AT ABOUT 1015HRS**



Figure A-1: View of Incident Site



Figure A-2: Pictorial View of Incident Site




Figure A-3: Schematics Legend




Figure A-4




Figure A-5




Figure A-6




Figure A-7




Figure A-8




Figure A-9



Figure B-1: Front View of MID35 / SJR 9174J



Figure B-2: Rear View of MID35 / SJR 9174J



Figure B-3: Left View of MID35 / SJR 9174J



Figure B-4: Right View of MID35 / SJR 9174J



Figure B-5: Zoomed-in View of MID35 / SJR 9174J



Figure B-6: Zoomed-in View of MID35 / SJR 9174J

Damage Assessment: Damage to front bumper/bonnet, cracked windscreen,
damage to Lamppost 163


STATEMENT OF	PNG YAP KAT, UELUIN				ALIASES	—			
NRIC NO	SP921866E	AGE	25		MALE/FEMALE	MALE			
EMPLOYMENT	REGULAR	DRIVING LICENCE NO			NATIONALITY	SINGAPOREAN			
DIALECT	HOKKIEN	LANGUAGE SPOKEN	ENGLISH		TEL NO	9727906			
ADDRESS	BLK H35, JURONG WEST STREET 42, #03-550, 8640435								
INTERPRETED BY		RANK		TIME		DATE		SIGN	
RECORDED BY		RANK		TIME		DATE		SIGN	
<p>On 25 Oct 2024, at approximately 1015hrs. I was driving the grade 1 staff car (SSB91745, 35 HED) along Upper Bukit Timah Rd after exiting BKE and turning right from Dairy Farm Rd towards Woodlands Rd. I was en route to MENDEE to collect documents for Chief of Air Force at Changi Air Base (West). After completing the right turn and traveling in the right lane for a bit, I kept left and nearing to completing the lane change. I suddenly blacked out and lost control of the vehicle. As a result, the vehicle mounted the kerb and ultimately collided with Lamp Post 163.</p>									
<p>The impact caused the following damage to the vehicle:</p> <ol style="list-style-type: none"> 1. Front bumper and bonnet were dented 2. All airbags were deployed 									
<p>Additionally, the collision resulted in damage to government property:</p> <ol style="list-style-type: none"> 1. Lamp Post 163 was uprooted and displaced 									
<p>I sustained minor injuries, including bruises on my lower left arm and scratches on my lower right arm.</p>									
<p>That is all I have to say.</p>									
DATE	28/10/24			SIGNATURE OF DRIVER/ WITNESS					

Figure C-1: Statement of Driver



**SINGAPORE
POLICE FORCE**



T/20241025/7076

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3
Report No. T/20241025/7076

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/10/2024 14:45		Vide Report No.: J/20241025/0035		Station Diary No.:	
Informant's Particulars					
Name of Informant: PNG YAP KAI,VELMUN			Address: 435 JURONG WEST STREET 42 #03-550 SINGAPORE 640435		
ID Type / ID No.: NRIC NO / S9921866E			Contact No.: Home/Office: Mobile: 97275906		
Nationality: SINGAPORE CITIZEN			Email: FREAKMASTER2012@HOTMAIL.COM		
Sex: Male	Age: 25	Date of Birth: 30/06/1999	Type of Informant: Driver		
Race: Chinese			Language: English		
Occupation: Singapore armed forces personnel			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 25/10/2024 11:00	Type of Location:
Location: HILLVIEW AVENUE				
Weather:		Road Surface:		
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.:	Type	Make	Model	Color	Condition	No of Passenger
SJR9174J	Motor car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Figure D-1



**SINGAPORE
POLICE FORCE**



T/20241025/7076

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20241025/7076

CONTINUATION OF REPORT

Driver			
Name	PNG YAP KAI,VELMUN		ID No. S9921866E
Related Vehicle	SJ9174J (Motor car)		Contact No. 97275906
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave (MC)	NIL		Degree of Injury NIL

Brief Details.

On 25 Oct 2024 at around 1015hrs, I was driving SJ9174J, a military staff car along Upper Bukit Timah Rd, to return to MINDEF from Changi Air Base (West). I was travelling along Dairy Farm Rd after exiting BKE and made a right turn to upper bukit timah rd (towards woodlands rd) towards MINDEF. After completing the right turn, I was travelling along the right lane of a two lane road, when I lost control of the vehicle and mounted onto a kerb on the left bypassing the left lane, coming to a stop after colliding with a lamp post.

Damages sustained on SAF vehicle included (1) front bumper and bonnet dented and (2) all airbags activated.

Damages sustained on government property included (1) lamp-post 163 uprooted and displaced.

I sustained minor bruises on my lower left arm and minor scratches on my lower right arm.

Figure D-2



**SINGAPORE
POLICE FORCE**



T/20241025/7076

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20241025/7076

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 25/10/2024 14:45
Officer In Charge Of Case: TP / TPIB / MOHAMAD BURHAN BIN SABTU Contact No.: 65476214	Classification Of Case:

NP168

Figure D-3