

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

Hui Rong.

EMPEROR LEASING PTE LTD
 1 KUNG CHONG ROAD
 SINGAPORE 159139

TAX INVOICE

Repair Code : CLM18503

Date in : 23/12/2024

Vehicle Num. : SNK2451U

Model : TOYOTA VOXY HYBRID 1.8X CVT

Chassis/Eng# : ZWR800281097/2ZR0A22542

Contact : 65436968, 80639739 96461147

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Checked</i>	1	841.20	841.20 ✓
REAR BUMPER END SEAL COVER LH <i>new</i>	1	138.00	138.00 +
REAR BUMPER LH REFLECTOR <i>new</i>	1	141.20	141.20 +
REAR BUMPER LH SIDE RETAINER <i>new</i>	1	86.10	86.10 +
REAR BUMPER TOW HOOK COVER <i>new</i>	1	32.10	32.10 +
REAR END PANEL <i>new</i>	1	1126.10	1,126.10 +
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	198.30	198.30 +
REAR END PANEL ANTENNA SENSOR WIRE HARNESS <i>new</i>	1	205.70	205.70 +
REAR LH BEARING <i>new</i>	1	637.50	637.50 +
REAR LH FENDER <i>Repis</i>	1	2179.30	2,179.30 +
REAR TAILLAMP LOWER GARNISH L/R <i>LH Defend</i>	2	176.80	353.60 <i>176.80</i>
REAR TAILLAMP LOWER GARNISH SIDE RETAINER L/R <i>new</i>	2	160.70	321.40 +
Subtotal before discount			6,260.50
Percentage discount 25%			1,565.13
Sub-total 1			4,695.38
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00 <i>30</i>
REAR BUMPER REVERSE SENSOR <i>new</i>	1	280.00	280.00 +
REAR LH SPORT RIM <i>new</i>	1	800.00	800.00 +

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

EMPEROR LEASING PTE LTD
1 KUNG CHONG ROAD
SINGAPORE 159139

TAX INVOICE

Repair Code : CLM18503

Date in : 23/12/2024

Vehicle Num. : SNK2451U

Model : TOYOTA VOXY HYBRID 1.8X CVT

Chassis/Eng# : ZWR800281097/2ZR0A22542

Contact : 65436968, 80639739 96461147

Subtotal before discount	1,130.00
Percentage discount 0%	0.00
Sub-total 2	1,130.00
Parts-total	5,825.38

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

80.00 50

To remove, reinstall fender glass

100.00 +

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.

180.00 +

To road test driving, check and resetting wheel alignments system.

100.00 +

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

80.00 +

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

800.00 50

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1,000.00 250

To apply anti-rust chemical on repaired and replaced panel.

80.00 +

Labour Total

2,420.00

Parts & Labour Total

8,245.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*** This is a computer-generated document which requires no signature.***

page 2

Adrian G
2/5 24/12/24
03 Rys

total: 1593.50
H/s: 1.2K ✓