



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2503733

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 16/06/2025
Reference CD/CTI24120359/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SNS 3330L
Insured Veh. SLS 4117D
Claim No. SNM24D207273
Policy No. DMHCSNA00006192401
Accident Date 23/12/2024
Inspection Date 24/12/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CD/CTI24120359/Upa3q2(N)	
			Date: 16/06/2025	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLS 4117D	Veh. Inspected	SNS 3330L
	Policy No.	DMHCSNA00006192401	Coverage (\$)	0.00
	Claim No.	SNM24D207273	Excess (\$)	0.00
	Assign From		Assign Date	24/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	RU11312991	Colour	PURPLE
	Odometer	158015 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R16	MICHELIN	6 mm
	L/H Front Tyre	225/50 R16	MICHELIN	6 mm
	R/H Rear Tyre	225/50 R16	MICHELIN	6 mm
	L/H Rear Tyre	225/50 R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/12/2024	Inspection Date	24/12/2024
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNS 3330L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	820.00	820.00
1	FRONT BUMPER SIDE RETAINER O/S	CRACKED	145.00	62.50
1	FRONT BUMPER LOWER SPOILER	DEFORMED / CUT	580.00	520.00
1	FRONT BUMPER UNDER COVER	NOT NECESSARY	390.00	-
1	FRONT BUMPER FOG LAMP O/S	CRACKED	560.00	322.40
1	FRONT BUMPER FOG LAMP GARNISH O/S	TWISTED	360.00	160.80
1	FRONT BUMPER REINFORCEMENT	BENT	420.00	321.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT GRILLE	CRACKED	860.00	480.00
1	FRONT GRILLE OUTER GARNISH	NOT NECESSARY	445.00	-
1	FRONT GRILLE 'H' LOGO	NOT NECESSARY	35.00	-
1	HEADLAMP O/S	HOLDER CRACKED	2,940.00	2,201.20
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	615.00	-
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	600.00	-
1	FRONT FENDER OUTER PROTECTOR O/S	DEFORMED / TORN	360.00	280.40
	LESS 20% DISCOUNT		-	-1,043.66
			9,180.00	4,174.64
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM.	NOT NECESSARY	100.00	-
	TO REFILL AIR CON GAS .	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL AND FRONT FENDER O/S .		600.00	320.00
	TO PUTTY & SPRAY PAINTING.		800.00	500.00
			1,670.00	840.00
	GRAND TOTAL		10,850.00	5,014.64

Report Ref No. CD/CTI24120359/Upa3q2(N)



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00
---	--	--	----------

Report Ref No. CD/CTI24120359/Upa3q2(N)

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L




PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L




PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 8 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L






PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L



PHOTOGRAPHS FOR VEHICLE NO. : SNS 3330L

