

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

Not Authorized
 in
 means
 24.2/24
 2/5 \$4000
 3 days
 the photo after repair

VEHICLE No: SNS 3330L

1PC	FRONT BUMPER	DD	\$820.00	✓
1PC	FRONT BUMPER SIDE RETAINER O/S	one	62.50 \$145.00	✓
1PC	FRONT BUMPER LOWER SPOILER	def/cut	520 \$580.00	✓
1PC	FRONT BUMPER UNDER COVER	in	\$390.00	X
1PC	FRONT BUMPER FOG LAMP O/S	one	322.40 \$560.00	✓
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	two	160.80 \$360.00	✓
1PC	FRONT BUMPER REINFORCEMENT	left	321.00 \$420.00	✓
1SET	FRONT BUMPER CLIPS	all	\$50.00	✓
1PC	FRONT GRILLE	one	480.00 \$860.00	✓
1PC	FRONT GRILLE OUTER GARNISH	in	\$445.00	X
1PC	FRONT GRILLE 'H' LOGO	in	\$35.00	X
1PC	HEADLAMP O/S	holder one	2221.20 \$2,940.00	✓
1PC	FRONT SUPPORT PANEL	R	\$615.00	X
1PC	FRONT FENDER O/S	R	\$600.00	X
1PC	FRONT FENDER OUTER PROTECTOR O/S	Return 280.40	\$360.00	✓
		(20%)	\$9,180.00	

TO CHECK WIRING
 TO RESET & REPROGRAMME DIAGNOSIS SYSTEM
 TO REFILL AIR CON GAS
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

\$50.00 20
 17 \$100.00 X
 17 \$120.00 X
 \$600.00 320
 \$800.00 500
TOTAL \$10,850.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-5 218-30
 202
 417464
 240
 501464
 202
 4011