Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way

51 Ubi Ave 1 #01-25 #09-16 Paya Ubi Industrial Park Singapore 408933 Singapore 079120

12 Feb 2025 Attn: Chu, Hui Yen Date:

Preliminary Advice

Vehicle No : SNU6328P Accident Date : 22/12/2024 Make : XPENG G6 Policy No. : 7240297885 **Assignment Date** : 24/12/2024 Excess : S\$4,200.00

: 7 Date of Inspection : 27/12/2024 Est. Duration of Repair

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

> 55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S	\$ 25,617	'.00 (inclusive supp \$4,280)
--------------------------------	-----------	-------------------------------

Revised Amount :S\$ 19.708.00 Check Items (Estimated) :S\$ 500.00 Total :S\$ 20,208.00

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 203,000.00 COE / PARF Rebate :S\$ 112,353.00

Salvage Value :S\$

Margin for Repair :S\$ 90,647.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(×	()	Other comments : Kindly approve check item inclusive supplementary.