



53 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PAXP/OD/0008/2024/KS
DATE : 27-Nov-24
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR TEO KIM SHENG (ZHANG JINSHENG)
ADDRESS : BLK 219 PASIR RIS STREET 21
#12-324
SINGAPORE 510210
TELEPHONE : HP +65 96912546
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7240297885
VEHICLE NO : SNU 6328 P
MODEL CODE : XPENG G6 RWD (LONG RANGE)
MODEL YEAR : 16/12/2024
ENGINE NO : E7KL044211030000GFA5
CHASSIS NO : L1NNSGHA0RB093135
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Dec-24
PLACE OF ACCIDENT : 633 VEERASAMY ROAD, SINGAPORE 200633

53 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE.SNU 6328 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO CARRY OUT DE-ENERGIZE HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION.	S/N \$	480.00	✓
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
3	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	600.00 300	
4	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,200.00 600	
5	TO RESPRAY FRONT BUMPER AND BOTH FRONT WHEEL ARCH TRIMS.	\$	2,300.00 1050	
6	TO CARRY OUT CALIBRATION FOR 360 DEGREE CAMERA SYSTEM.	\$	800.00	✓
7	TO PROVIDE PAINT PROTECTION FILM FOR AFFECTED AREA.	\$	1,360.00	✓
8	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	480.00	✓
TOTAL LABOUR CHARGES		: \$	8,700.00	

Cal-h



53 UBI ROAD 1, SINGAPORE 408690
TEL: 6386 2323 FAX: 6841 1183
EMAIL: NORA.XIA@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG



AIG

- Adrian

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNU 6328

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>torn</i>	1	\$ 773.00	✓ 618.4
2	FRONT BUMPER LOWER SPOILER <i>Dehnd</i>	1	\$ 26.00	✓ 20.8
3	FRONT PARKING AID SENSOR <i>Xt m</i>	1	\$ 80.00	X
4	FRONT BUMPER LOWER GRILLE <i>cracked</i>	1	TBC	✓ 156.00 204.8
5	FRONT BUMPER SIDE GUIDE - RH <i>new</i>	1	\$ 2.00	X
6	FRONT BUMPER TRIM - RH <i>ut</i>	1	\$ 29.00	✓ 23.2
7	FRONT DAYLIGHT - RH <i>Xt m</i>	1	\$ 1,927.00	X
8	HEADLIGHT - RH <i>cracked</i>	1	\$ 8,329.00	✓ 6663.2
9	FRONT WHEEL ARCH TRIM - LH / RH <i>new</i>	2	\$ 652.00	✓ 521.6
10	FRONT BUMPER LOWER COVER <i>cracked</i>	1	\$ 63.00	✓ 50.4
11	SUNDRIES <i>nec</i>		\$ 500.00	✓ 1.6
TOTAL SPARE PARTS		:	\$ 12,381.00	
TOTAL LABOUR CHARGES		:	\$ 8,700.00	
GRAND TOTAL		:	\$ 21,081.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

+ 3 days



TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

NAME : Adnan Ly
SURVEYED DATE : 27/12/24
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 04 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PAXP/OD/0008/2024/KS
7-Feb-25
GLORY
1 of 1
SNU 6328 P
XPENG G6 RWD (LONG RANGE)

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	\$ 1,800.00	✓
2	TO RENEW LOCK CARRIER AND ALIGN TO POSITION	\$ 1,500.00	1250.
<u>Parts</u>			
1	FRONT LOCK CARRIER <i>Crackd.</i>	\$ 713.00	✓ 570.4
2	FRONT WHEEL HOUSING LINER RHS <i>torn</i>	\$ 127.00	✓ 101.6
3	FRONT FOG LAMP COVER <i>Defect</i>	\$ 5.00	✓ 4
4	READY MIX COOLANT 4L <i>New</i>	\$ 135.00	✓ 108
GRAND TOTAL		\$ 4,280.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Ling
SLG

Add 3 days for the replacement of Lock Carrier.