

REF: CS/AIG24120360/Anp3 (SNU 6328P)

### ASSIGNMENT

Front: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estin: \_\_\_\_\_  
 OD / ~~RES~~ / TP RES / OD RES / EVA / INV / MV  
 To in ~~Vehicle~~ No: \_\_\_\_\_  
 at W ~~Vehicle~~ / m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum ~~INS~~ ~~Use~~ \_\_\_\_\_ Excess: 4200  
 (Client's Record)  
 Make of Vek: \_\_\_\_\_

Veh No: SNU6328P Yr Regn: 2024 / Dec  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or X Peng G6  
 Make: Xiao Peng C.D. ✓  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 185 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: LXNSGH AOR B09.3135  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In Order / Jammed / Leaked / Burnt or  
 Brake: In Order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 255/45 R20  
 R: 255/45 R20

Remark: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

☒ / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or XP  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 27/12/24  
 Survey held at XPremium BEV  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Front o/s  
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repair: 7 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Date / Time	Action / Instruction
	OD AIG.
	COE Expiry :
	We will be advising our principal a cost of repair of \$17,488.00 before excess \$4,200 & GST with 7 repair days, subject to their approval.
	Estimate given during : Yes (✓)
	1st Survey : No ( )
	MV : <u>2031C</u> (red, \$8129,31%)
	PV : <u>112 HK</u>
	Nett: <u>90.6K</u>

Date/Time, File Pass to? ☐ : Preli. Report  
☐ : Final Report  
 Date/Time, File Return to?  
 Days Of Repair: 7  
 Resurvey No. of Trip: \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Others: \_\_\_\_\_  
 Addl Fee: ☐ : Site Insp (\$ )  
☐ : Interview (\$ )  
☐ : Tech. Invs (\$ )



53 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PAXP/OD/0008/2024/KS  
DATE : 27-Nov-24  
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/12/2024

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR TEO KIM SHENG (ZHANG JINSHENG)  
ADDRESS : BLK 219 PASIR RIS STREET 21  
#12-324  
SINGAPORE 510210  
TELEPHONE : HP +65 96912546  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 7240297885  
VEHICLE NO : SNU 6328 P  
MODEL CODE : XPENG G6 RWD (LONG RANGE )  
MODEL YEAR : 16/12/2024  
ENGINE NO : E7KL044211030000GFA5  
CHASSIS NO : L1NNSGHA0RB093135  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 22-Dec-24  
PLACE OF ACCIDENT : 633 VEERASAMY ROAD, SINGAPORE 200633

53 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE.SNU 6328 P**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO CARRY OUT DE-ENERGIZE HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION.	S/N \$	480.00	✓
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
3	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	<del>600.00</del> 300	
4	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	<del>2,200.00</del> 600	
5	TO RESPRAY FRONT BUMPER AND BOTH FRONT WHEEL ARCH TRIMS.	\$	<del>2,300.00</del> 1050	
6	TO CARRY OUT CALIBRATION FOR 360 DEGREE CAMERA SYSTEM.	\$	800.00	✓
7	TO PROVIDE PAINT PROTECTION FILM FOR AFFECTED AREA.	\$	1,360.00	✓
8	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	480.00	✓
<b>TOTAL LABOUR CHARGES</b>		: \$	<b>8,700.00</b>	

53 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNU 6328 P.**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>torn</i>	1	\$ 773.00	✓
2	FRONT BUMPER LOWER SPOILER <i>?</i>	1	\$ 26.00	?
3	FRONT PARKING AID SENSOR <i>Not m</i>	1	\$ 80.00	X
4	FRONT BUMPER LOWER GRILLE <i>cracked</i>	1	TBC	✓
5	FRONT BUMPER SIDE GUIDE - RH <i>Not m</i>	1	\$ 2.00	X
6	FRONT BUMPER TRIM - RH <i>lit</i>	1	\$ 29.00	✓
7	FRONT DAYLIGHT - RH <i>Not m</i>	1	\$ 1,927.00	X
8	HEADLIGHT - RH <i>cracked</i>	1	\$ 8,329.00	✓
9	FRONT WHEEL ARCH TRIM - LH / RH <i>New</i>	2	\$ 652.00	✓
10	FRONT BUMPER LOWER COVER <i>?</i>	1	\$ 63.00	?
11	SUNDRIES <i>?</i>		\$ 500.00	?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 12,381.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 8,700.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 21,081.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS.XPENG@PREMIUMAUTO.COM.SG

NAME : Adnan Ly  
SURVEYED DATE : 27/12/24  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : Not Authorised, 04 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT



**GK DETAILING**

# QUOTATION

**BILL TO :**

Name : Mr Teo  
Mobile : 9691 2546

DATE : 23 December 2024  
Quote No: 20240022

Vehicle Make/Model/Colour : XPENG / G6 White  
Vehicle Registration Number : SNU 6328 P

DESCRIPTION	AMOUNT
Magnus Pro Gloss PPF installation @	
Headlight	\$ 130.00
Front Bumper	\$ 1,080.00
Labour	\$ 150.00
*Subjected to paintwork in original condition after defective PPF is removed Need 2 working days to complete	
	\$ 1,360.00

GK Detailing Pte Ltd | 25 Kaki Bukit Rd 4, #06-59, Synergy @ Kaki Bukit, Singapore 417800  
T: +65 9155 1806 / +65 9658 8936 | E: info@ace-gk.com




# INVOICE

**BILL TO :**

Name : Mr Teo  
Contact Number : 9691 2546  
Vehicle Make/Model/Colour : XPENG / G6 White  
Vehicle Registration Number : SNU 6328 P

DATE : 20 December 2024  
INVOICE : INV02751

Payment Mode : CASH / BANK/TT

DESCRIPTION	AMOUNT
<b>Magnus Pro Optimum Paint Protection Film</b> Full Exterior Gloss	\$ 5,300.00
<b>Magnus Pro Nano-Ceramic Window Film Package</b> N.A	
<b>Nanonix Ceramic Coating</b> Non - PPF installed exterior Panel	
Discount	
Booking Deposit Paid :	
 UOB GK DETAILING PTE. LTD. SCAN TO PAY	
Magnus PRO Warranty :MP20241220303 Nanonix Warranty :	
Magnus Pro Paint Protection Film (PPF) Warranty 6 Years* against Bubbles, Cracking, and Delaminating	
*This warranty does not extend coverage to damage caused by normal wear and tear, environmental damages, road debris impact, accidents, collisions or intentional damage of any kind.	
Amount PAID :	\$ 5,300.00

GK Detailing Pte Ltd | 25 Kaki Bukit Rd 4, #06-59, Synergy @ Kaki Bukit, Singapore 417800  
T: +65 9155 1806 / +65 9658 8936 | E: info@ace-gk.com