

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TP INC
VERON.

CHEW TEE YEW
BLK 445A BUKIT BATOK WEST AVE 8
#22-431
SINGAPORE 651445

TAX INVOICE

Repair Code : CLM16524

Date in : 23/12/2024

Vehicle Num. : SMD9888X

Model : HONDA STEP WAGON SPADA E:HEV

Chassis/Eng# : RP81063490/LFA2253500

Contact : 84589888

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Regis</i>	1	1850.90	+ 1,850.90
REAR BUMPER INNER BRACKET <i>new</i>	1	317.50	+ 317.50
REAR BUMPER OUTER CHROME MOULDING (CENTER) <i>new</i>	1	390.80	+ 390.80
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	45.60	+ 91.20
REAR END PANEL <i>new</i>	1	977.40	+ 977.40
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	112.50	+ 112.50
REAR END PANEL BUZZLE SENSOR <i>new</i>	1	153.70	+ 153.70
REAR END PANEL INNER TOP GARNISH <i>new</i>	1	329.60	+ 329.60
REAR TAILGATE <i>Dent</i>	1	2570.70	✓ 2570.70 <i>2110</i>
REAR TAILGATE 'E:HEV' EMBLEM <i>new</i>	1	95.70	+ 95.70
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	88.50	✓ 88.50
REAR TAILGATE 'SPADA' EMBLEM <i>new</i>	1	99.20	✓ 99.20
REAR TAILGATE 'STEPWAGON' EMBLEM <i>new</i>	1	101.10	✓ 101.10
REAR TAILGATE HINGES L/R <i>new</i>	2	117.50	+ 235.00
REAR TAILGATE INNER RUBBER STOPPER L/R <i>new</i>	2	21.20	+ 42.40
REAR TAILGATE INNER TRIM BOARD <i>new</i>	1	817.50	+ 817.50
REAR TAILGATE LOWER OUTER GARNISH <i>new</i>	1	754.40	✓ 754.40
REAR TAILGATE LOWER OUTER GARNISH REVERSE SENSOR <i>new</i>	4	324.20	+ 1,296.80

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHEW TEE YEW
BLK 445A BUKIT BATOK WEST AVE 8
#22-431
SINGAPORE 651445

Contact : 84589888

TAX INVOICE

Repair Code : CLM16524

Date in : 23/12/2024

Vehicle Num. : SMD9888X

Model : HONDA STEP WAGON SPADA E:HEV

Chassis/Eng# : RP81063490/LFA2253500

REAR TAILGATE LOWER OUTER GARNISH REVERSE SENSOR 'O' RING	4	20.00	80.00
REAR TAILGATE LOWER OUTER GARNISH SPONGE	1	56.00	56.00
REAR TAILGATE MECHANISM LOCK	1	3429.50	441.50
REAR TAILGATE WEATHER STRIP	1	2743.60	287.20
REAR TAILGATE WINDSCREEN MOULDING	1	180.60	180.60
Subtotal before discount			11,370.20
Percentage discount 20%			2,274.04
Sub-total 1			9,096.16
REAR BUMPER CLIPS - SET	1	50.00	50.00
REAR BUMPER TOP CHROME PLATE	1	200.00	200.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	30.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	30.00	30.00
REAR TAILGATE LOWER OUTER GARNISH CLIPS - SET	1	30.00	30.00
REAR TAILGATE NUMBER PLATE	1	80.00	80.00
REAR TAILGATE NUMBER PLATE FRAME	1	50.00	50.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CHEW TEE YEW
BLK 445A BUKIT BATOK WEST AVE 8
#22-431
SINGAPORE 651445

Contact : 84589888

TAX INVOICE

Repair Code : CLM16524

Date in : 23/12/2024

Vehicle Num. : SMD9888X

Model : HONDA STEP WAGON SPADA E:HEV

Chassis/Eng# : RP81063490/LFA2253500

Subtotal before discount	550.00
Percentage discount 0%	0.00
Sub-total 2	550.00
Parts-total	9,646.16

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	2,710.00
Parts & Labour Total	12,356.16

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
r/s 24/12/24
03 Dmy
Total: 4123.60
r/s : 3.2K ✓