

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TP INC
 Veron.

TWINCAR LEASING PTE LTD
 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

TAX INVOICE

Repair Code : CLM16487
 Date in : 25/11/2024
 Vehicle Num. : SMK4104X
 Model : HONDA FIT HYBRID 1.5 AUTO
 Chassis/Eng# : GP51335614/LEB1442846

Contact : 98528918

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Delat</i>	1	893.70	893.70 595
REAR BUMPER CENTER GARNISH <i>Emulid</i>	1	78.00	78.00 +
REAR BUMPER REFLECTOR GARNISH L/R <i>new</i>	2	59.00	118.00 x
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	18.90	37.80 +
REAR BUMPER SPONGE L/R <i>in 2H crated</i>	2	69.00	138.00 69
REAR END PANEL <i>Repair</i>	1	469.00	469.00 +
REAR END PANEL ANTENNA SENSOR <i>touchid</i>	1	80.00	80.00 2
REAR END PANEL BUZZLE SENSOR <i>touchid</i>	1	85.00	85.00 2
REAR END PANEL INNER TOP GARNISH <i>new</i>	1	160.00	160.00 +
REAR TAILGATE <i>Detat</i>	1	1080.70	1,080.70 +
REAR TAILGATE 'FIT' EMBLEM <i>new</i>	1	35.00	35.00 +
REAR TAILGATE INNER PULL HANDLE <i>new</i>	1	25.00	25.00 x
REAR TAILGATE INNER TRIM BOARD <i>new</i>	1	210.00	210.00 +
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	157.00	157.00 -
REAR TAILGATE WEATHER STRIP <i>new</i>	1	92.30	92.30 2
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>	1	120.00	120.00 -

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 98528918

TAX INVOICE

Repair Code : CLM16487
 Date in : 25/11/2024
 Vehicle Num. : SMK4104X
 Model : HONDA FIT HYBRID 1.5 AUTO
 Chassis/Eng# : GP51335614/LEB1442846

	Subtotal before discount		3,779.50
Percentage discount	20%	2392	755.90
	Sub-total 1	1913.60	3,023.60
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00 <i>30</i>
REAR BUMPER REVERSE SENSOR - SET <i>end</i>	1	250.00	250.00 <i>20</i>
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	40.00	40.00 <i>+</i>
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	50.00 <i>+</i>
REAR TAILGATE NUMBER PLATE <i>new</i>	1	25.00	25.00 <i>5</i>
REAR TAILGATE NUMBER PLATE HOLDER <i>new</i>	1	50.00	50.00 <i>+</i>
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	60.00 <i>✓</i>
	Subtotal before discount		525.00
Percentage discount	0%		0.00
	Sub-total 2		525.00
	Parts-total		3,548.60

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00 ✓
To remove, reinstall tailgate windscreen	150.00 <i>120</i>
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80.00 <i>30</i>
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00 <i>600</i>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,000.00 <i>500</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 98528918

TAX INVOICE

Repair Code : CLM16487
 Date in : 25/11/2024
 Vehicle Num. : SMK4104X
 Model : HONDA FIT HYBRID 1.5 AUTO
 Chassis/Eng# : GP51335614/LEB1442846

To apply anti-rust chemical on repaired and replaced panel.		100.00	30
To remove, reinstall tailgate mechanism and check for function	1390	80.00	60
	Labour Total	2,490.00	
	Parts & Labour Total	6,038.60	

*** This is a computer-generated document which requires no signature.***

page 3

Adrian Lj
 L/S 24/12/24
~~24 Days~~
 No of days 284 Days
 total: 3593.60
 L/S: 28K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: