



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897 ATTN: LIM JUN HUA			Ref: CS/ICS24120364/Aqp3e2(N) Date: 23/10/2025 Code: AIS	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SNM 4283P	Veh. Inspected	PC 2887P	
Policy No.		Coverage (\$)	0.00	
Claim No.	2025 46002200	Excess (\$)	0.00	
Assign From	LIM JUN HUA	Assign Date	19/10/2025	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE COMMUTER	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KDH2230020763	Colour	BLACK	
Odometer	433334 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	WANLI	6 mm	
L/H Front Tyre	195 R15C	WANLI	6 mm	
R/H Rear Tyre	195 R15C	WANLI	6 mm	
L/H Rear Tyre	195 R15C	WANLI	6 mm	
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
Accident Date	12/12/2024	Inspection Date	24/12/2024	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	