

GOLD

Tr

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Xiao Chen.

Vehicle number: PC2887P

Make & Model: Toyota Hiace

Chassis number: KDH2230020763

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate centre emblem	1	\$ 83.10
2	Tailgate "GL" emblem	1	\$ 44.90
3	Tailgate "Hiace" emblem	1	\$ 67.80
4	Rear bumper	1	\$ 669.10
5	Rear bumper clips	1set	\$ 70.00
6	Rear bumper RH side retainer	1	\$ 77.30
7	RH taillamp assy	1	\$ 404.70
8	RH taillamp panel	1	\$ 178.40
9	RH taillamp lock clips	1set	\$ 35.00
10	RH taillamp lower cover	1	\$ 157.90
11	RH taillamp lower cover retainer	1	\$ 77.30
12	RH rear fender	1	\$ 1,765.70
13	Exhaust silencer	1	\$ 818.90

934.30

700.73

\$ 4,450.10
 Part less 25% \$ 1,112.53
 Total: \$ 3,337.58

No.	Special Nett Items	Qty	Amount S\$
1	Tailgate "70km/h" sticker	1	\$ 28.00
2	Rear RH fender joint sealant	1	\$ 70.00

Total: \$ 98.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and	\$ 1,400.00

3W

	realign all affected panels and areas		
2	Spray painting on affected areas and panels	\$	1,200.00
3	Check wiring and lighting system on affected areas	\$	70.00
4	Apply rust coating chemical on affected areas and panels	\$	80.00
5	Remove and reinstall rear garnish and boards to assist repair	\$	220.00
6	Remove and replace exhaust silencer to assist repair	\$	180.00

860 Total: \$ 1,750.00
 Agreed Amount: _____ (Part by Part / Lump sum)
 Working days: _____

Total: 1560.73

US \$ 1200 ✓

Spare Parts: \$ 3,337.58
 Special Nett: \$ 98.00
 Labour: \$ 1,750.00
 Total: \$ 5,185.58

Adm C
 2/5 24/12/24

03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer