

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDK 11M

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BEARING LH | NOT NECESSARY | 600.70 | - |
| 1 | FRONT HEADLAMP LH | CRACKED | 5,200.00 | 3,249.00 |
| 1 | FRONT HEADLAMP LOWER BRACKET RH | NOT NECESSARY | 145.40 | - |
| 1 | FRONT HEADLAMP SPONGE RH | NOT NECESSARY | 63.80 | - |
| 1 | FRONT BUMPER | DEFORMED | 2,340.20 | 2,180.00 |
| 1 | FRONT BUMPER SIDE RETAINER L | NOT NECESSARY | 286.20 | - |
| 1 | FRONT FENDER LH | TO REPAIR SEE LABOUR | 1,587.00 | - |
| | LESS 10% DISCOUNT | | -1,022.33 | -542.90 |
| | | | 9,200.97 | 4,886.10 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRONT WHEEL RIM LH (SN) | сит | 1,800.00 | 1,000.00 |
| 1 | FRONT LH TYRE (SN) | NOT NECESSARY | 450.00 | - |
| 1 | SET FRONT BUMPER CLIP (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | FRONT FENDER INNER SHIELD CLIP RH (SN) | NOT NECESSARY | 50.00 | - |
| | | | 2,350.00 | 1,050.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE & REFIX ACCIDENT DAMAGED PARTS & REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH. | | 800.00 | 400.00 |
| | TO SPRAY PAINT ON ACCIDENT AFFECTED AREA. | | 800.00 | 400.00 |
| | ALIGNMENT. | | 120.00 | 80.00 |
| | TO CHECK WIRING & REWIRE PARKING SENSOR. | | 80.00 | 50.00 |
| | TO DIAGNOSIS & RESET AFTER WORK. | NOT NECESSARY | 400.00 | - |
| | | | 2,200.00 | 930.00 |
| | GRAND TOTAL | | 13,750.97 | 6,866.10 |

Report Ref No. CS/FCI24120367/Anp3e2(N)



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 5,500.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CS/FCI24120367/Anp3e2(N)

MARKET VALUE: \$74,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$39,612.00=NETT VALUE: \$34,388.00



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatspever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.