

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TP 1st Cap.
Hui Rong

SAJAB4AX4JCP36426

ESTIMATE OF REPAIR

Veh# : SDK11M

Model:

JAGUAR XE

Accident Date : 11/12/2024

(28/9/2018 - 27/9/2028)

Location : RIVERVALE LINK

SP:

SHD7040Y (1ST CAP)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front wheel rim LH <i>cut</i>		1800.00	1000/snw
2	1 pc	Front bearing LH <i>new</i>	600.70		
3	1 pc	Front Lh tyre <i>new</i>		450.00	+
4	1 pc	Front headlamp Lh <i>Cracked</i>	5200.00	3075	3249
5	1 pc	Front headlamp lower bracket RH <i>new</i>	145.40	+	
6	1 pc	Front headlamp sponge RH <i>new</i>	63.80	+	
7	1 pc	Front bumper <i>Scratched</i>	2340.20	2180	
8	1 pc	Front bumper side retainer L <i>new</i>	286.20	+	
9	1 set	Front bumper clip <i>new</i>		50.00	✓
10	1 pc	Front fender Lh <i>Repair</i>	1587.00	+	
11	1 pc	Front fender inner shield clip RH <i>new</i>		50.00	+
Sub Total:			10,223.30	2,350.00	0.00
			10%	0%	0%
After Less %:			9,200.97	2,350.00	0.00
Labour					
1		To remove & refix accident damaged parts & realign accident affected area.	800.00	400	
2		To spray paint on accident affected area.	800.00	400	
3		Alignment	120.00	80	
4		To check wiring & rewire parking sensor. <i>930</i>	80.00	50	
5		To diagnosis & reset after work.	400.00	+	
Sub Total:			2,200.00		
Total:			13,750.97		
After less 20%:			11,000.78		

Acknowledged by Repairer

Signature:

Chan Gen Choon

Director

DipEng. AAE MIMI,MSAE(Aust)



AL 8778 1999
24 hr accident call



SDK11M ESTIMATEPg1

55K

Adrian Lim
1/s 26/12/24

03Days

Total: 6866.10
1/s: 55K