

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-36/37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

ESTIMATE COST OF REPAIR

Date: 23-Dec-24

Estimate no. 1568

Plate No. FBJ1051S

Model. R15V

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	Exhaust CAP	\$ 45.00	✓	
2	PROTECTOR	\$ 85.00	✓	
3	SHIFT PEDAL	\$ 125.00	✓	
4	STEERING CONE	\$ 180.00	✓	
5	FRONT FORK (L, H)	\$ 850.00	✓	
6	FRONT FORK (R, H)	\$ 850.00	✓	
7	UNDER BRACKET COMPS	\$ 280.00	✓	
8	HANDLE BAR (L, H)	\$ 85.00	✓	
9	HANDLE BAR (R, H)	\$ 85.00	✓	
10	LEVER CLUTCH	\$ 28.00	✓	
11	LEVER BRAKE	\$ 28.00	✓	
12	FRONT FOOTREST R	\$ 45.00	✓	
13	FRONT FOOTREST L	\$ 45.00	✓	
14	PEDAL BRAKE	\$ 85.00	✓	
15	BRACKET 2	\$ 125.00	✓	
16	BRACKET 1	\$ 125.00	✓	
17	BODY FRONT UPPER	\$ 185.00	✓	
18	REAR FLASHER LIGHT	\$ 45.00	✓	
19	FRONT FLASHER LIGHT R	\$ 45.00	✓	
20	FRONT FLASHER L	\$ 45.00	✓	
21	FRONT ACE	\$ 45.00	✓	
22	COVERSET	\$ 2,000.00	✓	
23	LABOUR	\$ 700.00	✓	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

Less 10% \$ 613.10
 Sub Total : \$ 5,517.90
 GST 9% \$ 496.61
 Total: \$ 6,014.51

2-3576
 10%
 3218.40
 320
 3538.4
 202
 2800

not Authorised
 nra
 90096608
 1/5 #2800
 change the key
 4 hrs.