



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|--|------------|
| MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: HARMINDER | | Ref: CS/FCI24120368/Unp3e2N) Date: 22/01/2025 Code: FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHA 9091C | Veh. Inspected | FBT 1051S |
| Policy No. | D-24101860MFCT | Coverage (\$) | 0.00 |
| Claim No. | D24010870MFCT | Excess (\$) | 0.00 |
| Assign From | HARMINDER | Assign Date | 24/12/2024 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | YAMAHA YZF 155 | c.c | 155 |
| Engine No. | HIDDEN | Year of Reg. | 2021 |
| Chassis No. | MH3RG721000001049 | Colour | BLUE |
| Odometer | 57122 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 110-70-17 | MICHELIN | 7 mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | 140-70-17 | MICHELIN | 7 mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S BODY. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 10/12/2024 | Inspection Date | 26/12/2024 |
| Survey held at | ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800 | | |
| 5a. Remarks | | | |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | |