

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 20.12.2024

TO : ECICS MOTOR CLAIMS DEPTS
VEHICLE NO : SLD9045Z
MODEL : MERCEDES C180K
DATE OF ACCIDENT : 19.12.2024
TIME OF ACCIDENT : 14:30 HOURS

Xiao Chen

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER NUMBER PLATE HOLDER <i>new</i>	1	\$ 274.00	\$ 274.00
2	FRONT BUMPER LOWER BRACKET <i>new</i>	2	\$ 98.00	\$ 196.00
3	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 799.00	\$ 799.00
4	FRONT BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 187.00	\$ 374.00
5	FRONT BUMPER REINFORCEMENT SIDE SUPPORT BRACKET <i>new</i>	2	\$ 94.00	\$ 188.00
6	FRONT FENDER INNER COWLING <i>ton</i>	2	\$ 159.00	\$ 318.00
7	FRONT HEADLAMP <i>cracked RH</i>	2	\$ 1,072.00	\$ 2,144.00
8	FRONT HEADLAMP PANEL <i>Best</i>	2	\$ 234.00	\$ 468.00
9	FRONT HEADLAMP PANEL TOP GARNISH <i>for RH</i>	2	\$ 174.00	\$ 348.00
10	BONNET LOGO <i>new</i>	1	\$ 68.00	\$ 68.00
11	BONNET HINGE <i>new</i>	2	\$ 87.00	\$ 174.00
12	BONNET BOTTOM LOCK <i>new</i>	2	\$ 148.00	\$ 296.00
13	BONNET STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00
14	FRONT RADIATOR TOP PANEL <i>new</i>	1	\$ 1,217.00	\$ 1,217.00
15	FRONT RADIATOR TOP PANEL GARNISH <i>cracked</i>	1	\$ 190.00	\$ 190.00
16	FRONT RADIATOR SUPPORT STAND PANEL <i>new</i>	2	\$ 178.00	\$ 356.00
17	FRONT TURBO COOLER <i>2x10</i>	1	\$ 1,726.00	\$ 1,726.00
18	FRONT TURBO COOLER HOSE <i>new</i>	1	\$ 203.00	\$ 203.00
19	AIR DUCT <i>new</i>	1	\$ 87.00	\$ 87.00

+
+
+
+
+
+
1072
234
174
+
+
+
+
+
+
+
+
+
+
+

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLD9045Z**
 MODEL : **MERCEDES C180K**
 DATE OF ACCIDENT : 19.12.2024
 TIME OF ACCIDENT : 14:30 HOURS

20	RADIATOR <i>Not new</i>	1	\$ 1,342.00	\$ 1,342.00	+
21	POWER STEERING OIL COOLER <i>new</i>	1	\$ 747.00	\$ 747.00	+
22	WIPER TANK <i>Not new</i>	1	\$ 149.00	\$ 149.00	+
23	AIRCON CONDENSER SIDE AIR GUARD <i>new</i>	2	\$ 86.00	\$ 172.00	+
24	AIRCON CONDENSER Not new <i>Depd</i>	1	\$ 1,282.00	\$ 1,282.00	✓
25	AIRCON HOSE <i>Not new</i>	1	\$ 496.00	\$ 496.00	+
26	COOLER AIR GUARD <i>Not new</i>	1	\$ 72.00	\$ 72.00	+
27	COOLER AIR PIPE <i>Not new</i>	2	\$ 157.00	\$ 314.00	+
28	FRONT ABS SENSOR RH <i>Not new</i>	1	\$ 386.10	\$ 386.10	+
29	FRONT KNUCKLE ARM RH <i>Depd</i>	1	\$ 770.00	\$ 770.00	✓
30	FRONT WHEEL HUP WITH BEARING RH <i>Depd</i>	1	\$ 460.00	\$ 460.00	✓
31	FRONT SHOCK ABSORBER RH <i>Best</i>	1	\$ 672.00	\$ 672.00	✓
32	FRONT LOWER ARM RH (FRONT) <i>Best</i>	1	\$ 774.00	\$ 774.00	✓
33	FRONT LOWER ARM RH (REAR) <i>Best</i>	1	\$ 699.00	\$ 699.00	✓
34	FRONT STABILIZER LINKAGE RH <i>new</i>	1	\$ 168.00	\$ 168.00	+
35	FRONT STEERING RACK & PINION <i>Best</i>	1	\$ 3,947.00	\$ 3,947.00	✓
36	FRONT CROSS MEMBER <i>Not new</i>	1	\$ 3,852.00	\$ 3,852.00	+
37	FRONT CROSS MEMBER BOTTOM COVER <i>new</i>	1	\$ 588.20	\$ 588.20	+
38	HEAD REST <i>Not new</i>	2	\$ 1,426.92	\$ 2,853.84	+

11459

10313.10

TOTAL PRICE \$ 29,208.14
 LESS 10% \$ 2,920.81
SUB TOTAL PRICE \$ 26,287.33

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER (SPECAIL TYPE) Disturbed	1	\$ 3,200.00	\$ 3,200.00
2	FRONT NUMBER PLATE Not new	1	\$ 50.00	\$ 50.00
3	FRONT BUMPER CLIP (SET) new	1	\$ 50.00	\$ 50.00
4	FRONT FENDER SET (SPECAIL TGYE) Storn	1	\$ 2,000.00	\$ 2,000.00
5	FRONT FENDER INNER COWLING CLIP (SET) new	1	\$ 50.00	\$ 50.00
6	FRONT RADIATOR TOP PANEL GARNISH CLIP (SET) new	1	\$ 50.00	\$ 50.00
7	BONNET (SPECAIL TYPE) Not new Regis	1	\$ 2,800.00	\$ 2,800.00
8	SIDE SKIRT SET(SPECAIL TYPE) Not new	1	\$ 2,000.00	\$ 2,000.00

TO : ECICS MOTOR CLAIMS DEPTS
 VEHICLE NO : SLD9045Z
 MODEL : MERCEDES C180K
 DATE OF ACCIDENT : 19.12.2024
 TIME OF ACCIDENT : 14:30 HOURS

9	SIDE SKIRT CLIP RH <i>new</i>	1	\$ 50.00	\$ 50.00
10	STICKER WRAPPING (SPECAIL TYPE)	1	\$ 2,800.00	\$ 2,800.00
11	WHEEL RIM RH <i>cut</i>	1	\$ 1,800.00	\$ 1,800.00
12	WHEEL TYRE RH <i>Punctured</i>	1	\$ 680.00	\$ 680.00
13	BRAKE OIL <i>3x2</i>	1	\$ 40.00	\$ 40.00
14	RADIATOR COOLANT <i>free</i>	1	\$ 180.00	\$ 180.00

TOTAL \$ 15,800.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,000.00	600
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	800
3	REFOCUS HEADLAMP BEAM	\$ 80.00	x
4	RESET HEAD REST	\$ 650.00	x
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	x
7	REMOVE AND REFIX TURBO COOLER	\$ 80.00	x
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	300
9	WIRING CHECK	\$ 250.00	30
10	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
11	FOUR WHEEL ALIGNMNET	\$ 120.00	80
12	RESET ABS LIGHT	\$ 600.00	x

5250

TO : **ECICS** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLD9045Z**
MODEL : **MERCEDES C180K**
DATE OF ACCIDENT : 19.12.2024
TIME OF ACCIDENT : 14:30 HOURS

13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 800.00	150
----	--	-----------	-----

2020

TOTAL

\$7,350.00

TOTAL PARTS COST : \$ 42,087.33
TOTAL LABOUR COST : \$ 7,350.00
TOTAL REPAIR COST : \$ 49,437.33

Adnan
1/s 24/12/24
08 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP :8297 9787

total: 17583.10
1/s: 14050 ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: