

REF:

CS/ICS24120371/Aqp3

ASSIGNMENT

From: _____ Date: _____

Estimate: _____

OD / TP / RES / OD RES / EVA / INV / MVTo in Vehicle No: _____at W/O km/s

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum INS Unit _____ Excess: _____

(Client's Record)

Make of Vehicle _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLD9045Z Yr Regn: 2008, JulyType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180K 1796Colour: Purple A/C: Insured / Std / NI / NASp. Reading: 273108 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD204062A157360Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/40 R18R: 225/40 R18

BS / DUN / EXNOVA / GY / FS / I / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 24/12/24Survey held at JL Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s, u/c.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP ECICS</u>
	<u>LS \$14050, 8 days (Red \$35337.33, 72%)</u>
	<u>MV: 37K</u>
	<u>PV: 16.1K</u>
	<u>Nett: 20.9K</u>
	<u>760J</u>

Date/Time, File Pass to? ☐ : Preli. Report1) 17/12 Typist ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Form: MER-TPReport Form: MER-TPDays Of Repair: 8Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Inve (\$)

Survey Fee:

Transportation:

3 + R.S. \$1

Photos

Others

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 20.12.2024

TO : ECICS MOTOR CLAIMS DEPTS
VEHICLE NO : SLD9045Z
MODEL : MERCEDES C180K
DATE OF ACCIDENT : 19.12.2024
TIME OF ACCIDENT : 14:30 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER NUMBER PLATE HOLDER <i>new</i>	1	\$ 274.00	\$ 274.00
2	FRONT BUMPER LOWER BRACKET <i>new</i>	2	\$ 98.00	\$ 196.00
3	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 799.00	\$ 799.00
4	FRONT BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 187.00	\$ 374.00
5	FRONT BUMPER REINFORCEMENT SIDE SUPPORT BRACKET <i>new</i>	2	\$ 94.00	\$ 188.00
6	FRONT FENDER INNER COWLING <i>ton</i>	2	\$ 159.00	\$ 318.00
7	FRONT HEADLAMP <i>cracked RH</i>	2	\$ 1,072.00	\$ 2,144.00
8	FRONT HEADLAMP PANEL <i>Best</i>	2	\$ 234.00	\$ 468.00
9	FRONT HEADLAMP PANEL TOP GARNISH <i>ton RH</i>	2	\$ 174.00	\$ 348.00
10	BONNET LOGO <i>new</i>	1	\$ 68.00	\$ 68.00
11	BONNET HINGE <i>new</i>	2	\$ 87.00	\$ 174.00
12	BONNET BOTTOM LOCK <i>new</i>	2	\$ 148.00	\$ 296.00
13	BONNET STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00
14	FRONT RADIATOR TOP PANEL <i>new</i>	1	\$ 1,217.00	\$ 1,217.00
15	FRONT RADIATOR TOP PANEL GARNISH <i>cracked</i>	1	\$ 190.00	\$ 190.00
16	FRONT RADIATOR SUPPORT STAND PANEL <i>new</i>	2	\$ 178.00	\$ 356.00
17	FRONT TURBO COOLER <i>2x4</i>	1	\$ 1,726.00	\$ 1,726.00
18	FRONT TURBO COOLER HOSE <i>new</i>	1	\$ 203.00	\$ 203.00
19	AIR DUCT <i>new</i>	1	\$ 87.00	\$ 87.00

+
+
-
+
+
✓
1072
234
174
-
+
+
+
+
+
+
+
+
+
+
+

TO : ECICS MOTOR CLAIMS DEPTS
 VEHICLE NO : SLD9045Z
 MODEL : MERCEDES C180K
 DATE OF ACCIDENT : 19.12.2024
 TIME OF ACCIDENT : 14:30 HOURS

20	RADIATOR <i>Not new</i>	1	\$ 1,342.00	\$ 1,342.00	+
21	POWER STEERING OIL COOLER <i>new</i>	1	\$ 747.00	\$ 747.00	+
22	WIPER TANK <i>Not new</i>	1	\$ 149.00	\$ 149.00	+
23	AIRCON CONDENSER SIDE AIR GUARD <i>new</i>	2	\$ 86.00	\$ 172.00	+
24	AIRCON CONDENSER Not new <i>Replaced</i>	1	\$ 1,282.00	\$ 1,282.00	✓
25	AIRCON HOSE <i>new</i>	1	\$ 496.00	\$ 496.00	+
26	COOLER AIR GUARD <i>new</i>	1	\$ 72.00	\$ 72.00	+
27	COOLER AIR PIPE <i>new</i>	2	\$ 157.00	\$ 314.00	+
28	FRONT ABS SENSOR RH <i>new</i>	1	\$ 386.10	\$ 386.10	+
29	FRONT KNUCKLE ARM RH ?	1	\$ 770.00	\$ 770.00	?
30	FRONT WHEEL HUP WITH BEARING RH ?	1	\$ 460.00	\$ 460.00	?
31	FRONT SHOCK ABSORBER RH ?	1	\$ 672.00	\$ 672.00	?
32	FRONT LOWER ARM RH (FRONT) ?	1	\$ 774.00	\$ 774.00	?
33	FRONT LOWER ARM RH (REAR) ?	1	\$ 699.00	\$ 699.00	?
34	FRONT STABILIZER LINKAGE RH <i>new</i>	1	\$ 168.00	\$ 168.00	+
35	FRONT STEERING RACK & PINION ?	1	\$ 3,947.00	\$ 3,947.00	?
36	FRONT CROSS MEMBER <i>new</i>	1	\$ 3,852.00	\$ 3,852.00	+
37	FRONT CROSS MEMBER BOTTOM COVER <i>new</i>	1	\$ 588.20	\$ 588.20	+
38	HEAD REST <i>Not new</i>	2	\$ 1,426.92	\$ 2,853.84	+

TOTAL PRICE \$ 29,208.14
 LESS 10% \$ 2,920.81
SUB TOTAL PRICE \$ 26,287.33

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER (SPECAIL TYPE) <i>Disturbed</i>	1	\$ 3,200.00	\$ 3,200.00	1800
2	FRONT NUMBER PLATE <i>Not new</i>	1	\$ 50.00	\$ 50.00	+
3	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	✓
4	FRONT FENDER SET (SPECAIL TGYPE) <i>torn</i>	1	\$ 2,000.00	\$ 2,000.00	1200
5	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
6	FRONT RADIATOR TOP PANEL GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
7	BONNET (SPECAIL TYPE) Not new <i>Reps</i>	1	\$ 2,800.00	\$ 2,800.00	+
8	SIDE SKIRT SET(SPECAIL TYPE) <i>new</i>	1	\$ 2,000.00	\$ 2,000.00	+

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLD9045Z**
 MODEL : **MERCEDES C180K**
 DATE OF ACCIDENT : 19.12.2024
 TIME OF ACCIDENT : 14:30 HOURS

9	SIDE SKIRT CLIP RH <i>MCW</i>	1	\$ 50.00	\$ 50.00	<i>X</i>
10	STICKER WRAPPING (SPECAIL TYPE)	1	\$ 2,800.00	\$ 2,800.00	<i>??</i>
11	WHEEL RIM RH <i>cut</i>	1	\$ 1,800.00	\$ 1,800.00	<i>900</i>
12	WHEEL TYRE RH <i>Purchased</i>	1	\$ 680.00	\$ 680.00	<i>250</i>
13	BRAKE OIL <i>free</i>	1	\$ 40.00	\$ 40.00	<i>+</i>
14	RADIATOR COOLANT <i>free</i>	1	\$ 180.00	\$ 180.00	<i>+</i>

TOTAL \$ 15,800.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,000.00	<i>600</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>800</i>
3	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>+</i>
4	RESET HEAD REST	\$ 650.00	<i>+</i>
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>60</i>
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>+</i>
7	REMOVE AND REFIX TURBO COOLER	\$ 80.00	<i>+</i>
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>?</i>
9	WIRING CHECK	\$ 250.00	<i>30</i>
10	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>+</i>
11	FOUR WHEEL ALIGNMNET	\$ 120.00	<i>80</i>
12	RESET ABS LIGHT	\$ 600.00	<i>+</i>

TO : **ECICS** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLD9045Z**
MODEL : **MERCEDES C180K**
DATE OF ACCIDENT : 19.12.2024
TIME OF ACCIDENT : 14:30 HOURS

13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 800.00	150
----	--	-----------	-----

TOTAL \$7,350.00

TOTAL PARTS COST : \$ 42,087.33
TOTAL LABOUR COST : \$ 7,350.00
TOTAL REPAIR COST : \$ 49,437.33

Adnan
1/s 24/12/24
08 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP :8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: