

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24120373/ENP3M4**Date:** 14/01/2025REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAB00501		
Claimant Vehicle No :	SHD3934U	Insured Vehicle No :	SLV3256B		
Date of Loss:	21/12/2024	Nature of Claim:	TP	Claim No:	M2407520

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3934U	Engine No:	G4LEJU154715
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU129452
Reg. Date:	11/12/2018 (Man. Year: 2018)	Odometer:	457433 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,090.56	1,662.40	3,428.16	67.34
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	2,420.00	1,650.00	770.00	31.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,522.56	3,324.40	4,198.16	55.81
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	7,522.56	2,650.00	4,872.56	64.77
+ GST 9.00/9.00% (S\$)	677.03	238.50	438.53	64.77
Nett Amount (S\$)	8,199.59	2,888.50	5,311.09	64.77

INSPECTION

Date of Assignment:	26/12/2024 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969
Date Inspected:	23/12/2024 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2025)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3934U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Broken	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Broken	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Broken	394.80 FL	*394.80 FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Bent	138.10 FL	*138.10 FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Bent	138.10 FL	*138.10 FL
7	1		*REAR BUMPER SIDE BRACKET LH	Not Necessary	55.80 FL	*- FL
8	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	55.80 FL	*- FL
9	1		*BOOTLID	Repair	2,549.70 FL	*- FL
10	1		*BOOTLID HYUNDAI PLATE	Not Necessary	24.30 FL	*- FL
11	1		*EMBLEM HYBRID	Necessary	24.30 FL	*24.30 FL
12	1		*EMBLEM – IONIQ	Necessary	31.30 FL	*31.30 FL
13	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL
14	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
15	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
16	1		*REAR PANEL GARNISH	Not Necessary	346.80 FL	*- FL
17	1		*REAR PANEL	Repair	532.00 FL	*- FL
18	1		*REAR BUMPER LOWER CTR MOULDING	Not Necessary	155.00 FL	*- FL
19	1		*REAR BUMPER UNDER CTR COVER	Not Necessary	225.00 FL	*- FL
20	1		*REAR NUMBER PLATE WITH TRIM COVER	Broken	55.00 F	*55.00 F
21	1		*BOOTLID COMFORT TEL NO STICKER	Necessary	40.00 F	*40.00 F
22	1		*BOOTLID COMFORT LOGO STICKER	Necessary	30.00 F	*30.00 F
23	1		*BOOTLID COMFORT APP STICKER	Necessary	30.00 F	*30.00 F
24	1		*REAR BUMPER REVERSE SENSOR	Broken	180.00 F	*180.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	6,279.45	1,994.25
- List Item Discount on L Items 20.00/20.00% (S\$)	1,188.89	331.85

Total Parts (S\$)	5,090.56	1,662.40
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	760.00
2	SPRAY PAINTING CHARGE	New	900.00	840.00
3	CHK ALL LIGHTING/ WIRING	New	60.00	30.00
4	REMOVE/REFIX BOOTLID GLASS	New	120.00	0.00
5	TUFF KOTE	New	60.00	20.00
6	TOTAL LABOUR	New	80.00	0.00
Gross Labour Cost (\$\$)			2,420.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >