



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

FINALIZATION ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Choon Tuck Kiong (Qin Deqiang) 469 Jurong West Street 41 #06-491 Singapore 640469 Mobile: 92346382
	Document No. 0	
	Document Date 07/01/2025	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ZVW40R	AWXEBW S3	16/11/2020	SGJ3932E	0	35786	79/DS/SGJ3932E

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU00J052480	2ZR2F84481	60	Ong Wen Hong	03/01/2025 8.00	07/01/2025 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:III TP VEH:SNH3335G DATE OF ACC:23/12/2024 NUMBER OF REPAIR DAYS:05 REPAIR DAYS SURVEY BY:STEVE LKK				50.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS	*			1584.00
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS	*			1312.00
5	B	BP-LAB2 TO CHECK WIRING SYSTEM	*			134.64
6	B	BP-LAB2 TO DRILL HOLE AND INSTALL REVERSE SENSOR	*			198.00
7	B	BP-LAB2 TO REMOVE AND TRANSFER BOOT COMPONENT TO NEW BOOT	*			594.00
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
9	B	BP-WS2 TO REMOVE AND INSTALL REAR WINDSCREEN	*			594.00
10	S	BP-SUBLET TO SUPPLY SOLAR FILM FOR REAR WINDSCREEN	0650			480.00
11	1	T52159-47912 COVER, RR BUMPER	1.00	855.40		855.40
12	2	S52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00
13	3	T52023-12240 REINFORCEMENT	1.00	334.00		334.00
14	4	T52015-47080 ARM SUB-ASSY, RR	1.00	243.00		243.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Choon Tuck Kiong (Qin Deqiang) 469 Jurong West Street 41 #06-491 Singapore 640469 Mobile: 92346382
	Document No. 0	
	Document Date 07/01/2025	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ZVW40R	AWXEBW S3	16/11/2020	SGJ3932E	0	35786	79/DS/SGJ3932E

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU00J052480	2ZR2F84481	60	Ong Wen Hong	03/01/2025 8.00	07/01/2025 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	5	T52016-47060 ARM SUB-ASSY, RR	1.00	243.00		243.00
16	6	T67005-47460 PANEL SUB-ASSY, BACK	1.00	1692.80		1692.80
17	7	T68105-47190 GLASS SUB-ASSY, BACK	1.00	1426.00		1426.00
18	8	L56117-50140 DAM, WINDOW GLASS	1.00	40.10		40.10
19	9	T75442-47080 PLATE, BACK DOOR	1.00	87.90		87.90
20	0	T75441-47130 PLATE, LUGGAGE COMPT	1.00	75.70		75.70
21	1	T76891-47040 SPOILER, RR NO.1	1.00	1175.80		1175.80
22	2	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
23	3	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
24	4	SPC507-47009 00 BACK SENSOR (PRIMER)	1.00	167.50		167.50

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	12,059.84
	Please acknowledge receipt of vehicle	Parts 6,815.20 Labour 4,764.64 Sublet 480.00 Lubrication/Fluid 0.00 Others 0.00	GST 9.00%	1,085.39
			Less	0.00
			Amount Due	13,145.23

Company Copy