

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: There had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ3584S Yr Regn: 2016 / Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HRV C.D. 1486.

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 449895 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRU18106X201088

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16.

R: 215/60R16.

BS / DUN / EXNOVA / GY / FS / I / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 05/12/24.

Survey held at JL Perfect.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/s, u/c.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chirn

MV: 321k

PV: A.6K

Nett: 12.4K.

COE Expiry

Estimate given during: Yes COE
1st Survey No C

8772

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format:

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Survey Fee:

Transportation:

B + R.S. \$

Photos

Others

CLAIM DETAIL - PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Disled</i>	1	\$ 927.50	\$ 927.50
2	FRONT BUMPER LOWER LIP <i>corn</i>	1	\$ 351.00	\$ 351.00
3	FRONT BUMPER LOWER RUBBER <i>new</i>	1	\$ 169.40	\$ 169.40
4	FRONT BUMPER FOGLAMP <i>LH cancelled</i>	2	\$ 327.70	\$ 655.40
5	FRONT BUMPER FOGLAMP COVER <i>LH cancelled</i>	2	\$ 49.00	\$ 98.00
6	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 189.00	\$ 189.00
7	FRONT BUMPER SIDE RETAINER <i>LH Eng'd</i>	2	\$ 23.00	\$ 46.00
8	FRONT BUMPER REINFORCEMENT <i>Disled</i>	1	\$ 321.00	\$ 321.00
9	FRONT TEMPERATURE SENSOR <i>new</i>	1	\$ 142.00	\$ 142.00
10	HORN <i>new</i>	1	\$ 105.00	\$ 105.00
11	ENGINE UNDER CENTER COVER <i>3 pieces</i>	1	\$ 589.10	\$ 589.10
12	ENGINE UNDER SIDE COVER LH	1	\$ 186.00	\$ 186.00
13	FRONT BATTERY WIRE HARNESS <i>new</i>	1	\$ 485.20	\$ 485.20
14	FRONT FENDER LH <i>Disled</i>	1	\$ 580.00	\$ 580.00
15	FRONT FENDER INNER GARNISH LH <i>new</i>	1	\$ 85.00	\$ 85.00
16	FRONT FENDER INNER COWLING <i>Disled</i>	2	\$ 130.00	\$ 260.00
17	FRONT FENDER ARCD GARNISH <i>Disled</i>	2	\$ 153.00	\$ 306.00
18	FRONT WHEEL HOUSE PANEL LH <i>Repair</i>	1	\$ 1,236.20	\$ 1,236.20
19	FRONT WHEEL HOUSE EXTEND PANEL LH <i>Repair</i>	1	\$ 794.10	\$ 794.10
20	FRONT WHEEL HOUSE SUPPORT PANEL LH <i>Disled</i>	1	\$ 486.70	\$ 486.70
21	HEADLAMP (LED) <i>LH cancelled</i>	2	\$ 1,859.40	\$ 3,718.80
22	HEADLAMP LOWER BRACKET <i>LH cancelled</i>	2	\$ 35.00	\$ 70.00
23	HEADLAMP SIDE BRACKET <i>new</i>	2	\$ 41.00	\$ 82.00
24	GRILLE CENTRE SUPPORT BRACKET <i>new</i>	1	\$ 49.00	\$ 49.00
25	GRILLE LOGO <i>new</i>	1	\$ 28.00	\$ 28.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLJ3584S
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 04.12.2024
 TIME OF ACCIDENT : 11:00 HOURS

26	GRILLE LOGO GARNISH <i>new</i>	1	\$ 289.00	\$ 289.00	+
27	CENTRE GRILLE <i>changed</i>	1	\$ 370.00	\$ 370.00	✓
28	CENTRE GRILLE (CHROME) <i>new</i>	2	\$ 89.00	\$ 178.00	+
29	BONNET <i>new</i>	1	\$ 1,026.00	\$ 1,026.00	+
30	BONNET LOCK <i>new</i>	1	\$ 178.00	\$ 178.00	+
31	BONNET INNER RUBBER (FRONT) ?	2	\$ 27.00	\$ 54.00	+
32	BONNET INNER RUBBER (SIDE)	2	\$ 29.00	\$ 58.00	+
33	BONNET INSULATOR	1	\$ 247.00	\$ 247.00	+
34	BONNET STOPPER <i>new</i>	2	\$ 19.50	\$ 39.00	+
35	BONNET STAND CLIP <i>new</i>	1	\$ 15.00	\$ 15.00	+
36	BONNET STAND HOLDER	1	\$ 15.00	\$ 15.00	+
37	BONNET HINGE	2	\$ 45.00	\$ 90.00	+
38	FRONT SUPPORT PANEL <i>Dented</i>	1	\$ 796.00	\$ 796.00	-
39	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 185.00	\$ 185.00	+
40	RADIATOR SIDE GARNISH <i>new</i>	2	\$ 68.00	\$ 136.00	+
41	AIR CON CONDENSER <i>new</i>	1	\$ 898.00	\$ 898.00	+
42	AIR DUCT <i>new</i>	1	\$ 142.00	\$ 142.00	+
43	AIR CLEANER RESONATOR <i>new</i>	1	\$ 360.00	\$ 360.00	+
44	AIR CLEANER RESONATOR DUCT <i>new</i>	1	\$ 150.00	\$ 150.00	+
45	FUSE BOX <i>changed</i>	1	\$ 769.00	\$ 769.00	✓
46	FRONT WHEEL RIM LH <i>cut</i>	1	\$ 1,120.00	\$ 1,120.00	450(SW)
47	FRONT ABS SENSOR LH <i>new</i>	1	\$ 180.00	\$ 180.00	+
48	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 586.50	\$ 586.50	+
49	FRONT LOWER ARM LH	1	\$ 474.70	\$ 474.70	?
50	FRONT LEVEL SENSOR LH <i>new</i>	1	\$ 284.60	\$ 284.60	+
51	FRONT KNUCKLE ARM LH	1	\$ 461.70	\$ 461.70	?
52	FRONT KNUCKLE ARM INNER BEARING LH ?	1	\$ 262.00	\$ 262.00	?
53	FRONT WHEEL HUP LH	1	\$ 379.40	\$ 379.40	?
54	FRONT LINKAGE LH <i>new</i>	1	\$ 65.00	\$ 65.00	+
55	FRONT STEERING RACK & PINION <i>new</i>	1	\$ 1,750.00	\$ 1,750.00	+

TOTAL PRICE \$ 23,519.30
 LESS 20% \$ 4,703.86
SUB TOTAL PRICE \$ 18,815.44

SPECIAL NETT ITEMS

SPECIAL NETT ITEMS				
S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BATTERY <i>new</i>	1	\$ 200.00	\$ 200.00
2	COOLANT <i>new</i>	1	\$ 80.00	\$ 80.00
3	BRAKE OIL <i>new</i>	1	\$ 80.00	\$ 80.00

TO
VEHICLE NO
MODEL

DATE OF ACCIDENT
TIME OF ACCIDENT

: **CHINA TAIPING** MOTOR CLAIMS DEPTS
: **SLJ3584S**
: HONDA VEZEL
: 04.12.2024
: 11:00 HOURS

4	FRONT BUMPER CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
5	FRONT BUMPER REINFORCEMENT TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
6	ENGINE UNDER CENTER COVER CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
7	FRONT FENDER COWLING CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
8	FRONT FENDER ARCD GARNISH CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	<i>20</i>
9	FRONT WIPER PANEL SIDE GARNISH CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
10	CENTRE GRILLE CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>20</i>
11	GRILLE LOGO GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
12	FRONT WIPER PANEL GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
13	FRONT SUPPORT PANEL SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
14	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>+</i>

TOTAL \$ 970.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>1000</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>800</i>
3	REMOVE AND REFIX WIREHARNESS AND WIRING CHECKING	\$ 180.00	<i>30</i>
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>60</i>
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>60</i>
6	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>+</i>
7	RESET ABS LIGHT	\$ 350.00	<i>+</i>
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>?</i>
9	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	<i>+</i>
10	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	<i>+</i>
11	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SLJ3584S
MODEL : HONDA VEZEL
DATE OF ACCIDENT : 04.12.2024
TIME OF ACCIDENT : 11:00 HOURS

12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$ 5,940.00

TOTAL PARTS COST : \$ 19,785.44
TOTAL LABOUR COST : \$ 5,940.00
TOTAL REPAIR COST : \$ 25,725.44

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
1/s 05/12/24
10 Days.