

SM INTEGRATED PTE LTD

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_INTEGRATED@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

UEN: 202235196G

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 06/12/2024

06/01/2025

TP ALG.
Yen.

Estimated repair cost for vehicle no: YQ9838E MITSUBISHI CANTER FEB21ER4SDEN

CHASSIS: FEB21EA36154 (2022)

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>new</i>	\$798.00	\$798.00 <i>x</i>
2	1	FRONT BUMPER SIDE GUIDE RH <i>2nd</i>	\$189.00	\$189.00 <i>+</i>
3	1	RH FRONT BUMPER BRACKET <i>1st</i>	\$254.00	\$254.00 <i>+</i>
4	1	RH FRONT HEADLAMP <i>2nd</i>	\$659.00	\$659.00 <i>✓</i>
5	1	RH FRONT SIDE LAMP <i>3rd</i>	\$326.00	\$326.00 <i>✓</i>
6	1	RH FRONT SIGNAL LAMP <i>3rd</i>	\$284.00	\$284.00 <i>✓</i>
7	1	RH FRONT HEADLAMP LOWER RUBBER <i>new</i>	\$38.00	\$38.00 <i>x</i>
8	1	RH FRONT CORNER PANEL <i>2nd</i>	\$689.00	\$689.00 <i>459</i>
9	1	RH FRONT CORNER PANEL INNER RUBBER <i>new</i>	\$36.00	\$36.00 <i>x</i>
10	1	FRONT GRILLE <i>cut</i>	<i>1187</i> \$1187.00	\$1187.00
11	1	FRONT GRILLE EMBLEM FUSO <i>new</i>	\$157.00	\$157.00 <i>✓</i>
12	1	FRONT PANEL <i>2nd</i>	<i>1451</i> \$1451.00	\$1451.00 <i>✓</i>
13	1	FRONT WIPER GARNISH <i>cracked</i>	<i>477</i> \$477.00	\$477.00 <i>✓</i>
14	1	RH FRONT STEP PANEL <i>2nd</i>	\$659.00	\$659.00 <i>x</i>
15	1	RH FRONT STEP PANEL GARNISH <i>1st</i>	\$589.00	\$589.00 <i>+</i>
16	1	RH FRONT ROUND MIRROR <i>2nd</i>	\$197.00	\$197.00 <i>x</i>
17	1	RH FRONT SQUARE MIRROR <i>1st</i>	\$215.00	\$215.00 <i>x</i>
18	1	RH FRONT MIRROR ARM <i>2nd</i>	\$408.00	\$408.00 <i>x</i>
19	1	RH FRONT MIRROR ARM COVER <i>1st</i>	\$152.00	\$152.00 <i>x</i>

5000

3750

25%

TOTAL :	\$7,921.00
LESS 10 %	\$792.10
SUB-TOTAL :	\$7,128.90

YQ9838E MITSUBISHI CANTER

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	LH FRONT HEADLAMP CLIPS <i>new</i>	\$18.00	<i>2</i> \$18.00 <i>4</i>
2	4	LH FRONT CORNER RUBBER CLIPS <i>new</i>	\$3.00	<i>+</i> \$12.00
3	1	LH FRONT HEADLAMP LOWER RUBBER CLIPS <i>new</i>	\$20.00	<i>+</i> \$20.00

TOTAL: \$50.00

TOTAL PARTS : \$7,178.90

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS

600 \$1,200.00
650 \$1,000.00
1280 *30* \$60.00
+ \$200.00

Subtotal :- \$2,460.00

Total:- \$9,638.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adm
h/s 06/01/25 -

04 Days

total: 503025

h/s 4K

4K