



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 ATTN: SHIANG YI			Ref: CS/SMO24120381/Knp3e2(N) Date: 21/01/2025 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGH 6194L	Veh. Inspected	SKA 3511L
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2404138/SYH	Excess (\$)	0.00
	Assign From	SHIANG YI	Assign Date	26/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	PORSCHE 911 CARRERA (A)	c.c	3614
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	WP0ZZZ99ZAS700139	Colour	METALLIC DARK BLUE
	Odometer	69826 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/35Z R19	PIRELLI	8 mm
	L/H Front Tyre	235/35Z R19	PIRELLI	8 mm
	R/H Rear Tyre	295/30Z R19	PIRELLI	9 mm
	L/H Rear Tyre	295/30Z R19	PIRELLI	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/12/2024	Inspection Date	26/12/2024
	Survey held at	160 SIN MING DRIVE #06-03 SIN MING AUTOCITY SINGAP		
	Repairer	KBS MOTORSPORTS PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	